POOR LEGIBILITY

PORTIONS OF THIS DOCUMENT MAY BE UNREADABLE, DUE TO THE QUALITY OF THE ORIGINAL



1927 LAKESIDE PARKWAY SUITE 614 TUCKER, GEORGIA 30084 404-938-7710

March 8, 1989

Mr. A.R. Hanke Site Investigation and Support Branch Waste Management Division Environmental Protection Agency 345 Courtland Street, N. E. Atlanta, Georgia 30365

Subject:

Preliminary Reassessment

Pullman Standard

Birmingham, Jefferson County, Alabama

EPA ID No. ALD004017729 TDD No. F4-8811-20

Dear Mr. Hanke:

FIT 4 conducted a preliminary reassessment of Pullman Standard Company in Birmingham, Alabama. The assessment included a review of EPA and state file material, completion of a target survey and a drive-by reconnaissance of the facility on December 1, 1988.

Pullman Standard has been fabricating steel in the production of railroad cars since 1929 (Ref. 1). This process involved welding, riveting, bolting, shot blasting, and painting. Waste products include waste paint and solvents including toluene and xylene. This facility closed in 1980 at which time all remaining waste products were removed from the site. At that time, Pullman Standard did not withdraw their RCRA interim status in the hope that the facility would be able to reopen or be bought out. In late 1983, Trinity Industries of Dallas, Texas, purchased the facility and operations resumed on September 1, 1984 (Ref. 1).

For approximately 10 years prior to ceasing operations, waste materials were kept in drums at the facility. During this time waste paints were kept in their original drums and placed in the facility yard. Before 1970, the waste paint materials were hauled from the site every 5-6 years. Before the mid 1960's, the painting was done outside and use of solvents was limited. In or around 1965, a building was erected to house the painting operations. At that time Pullman Standard began using more solvents to clean the reusable stencils. The method of disposal of these waste materials is uncertain. There are no records indicating any onsite disposal of hazardous waste. Currently, Pullman is classified as a hazardous waste generator under RCRA. The company withdrew its Part B application as a storage facility (Ref. 2).

Pullman Standard is located in the Birmingham Valley physiographic section of the Valley and Ridge Physiographic Province (Ref. 3). The area is characterized by northeast-southwest trending valleys and ridges, which exhibit extensive faulting and folding (Ref. 3, pp. 1, 3). As a result of these structural features vast differences in geologic and hydrogeologic environments occur over distances of only a few miles (Ref. 3, p. 1). Groundwater occurs in solution cavity channels and fracture zones

Per 18/89 3/13/89 C-586-3-9

4 1047

Las La

Date:	
Site Disposition:	
EPA Project Manager:	
-	

REFERENCES

- 1. Potential Hazardous Waste Site Preliminary Assessment (EPS forms 3012-II and 3012-111) for Pullman Standard.
- 2. Joe Downey, Alabama Department of Environmental Management, telephone conversation with Bob Tolford, NUS Corporation, December 12, 1988. Subject: RCRA status of four Alabam sites.
- 3. T. B. Moffett, and P. H. Moser, <u>Groundwater Resources of the Birmingham and Cahaba Valleys of Jefferson County</u>, <u>Alabama</u>, Circular 103, (University, Alabama: Geological survey of Alabama, 1978), pp. 1-44.
- 4. W. D. Johnson, <u>Groundwater in the Palozoic Rocks of Northern Alabama</u>, Special Report No. 16, (Geologic Survey of Alabama, 1933).
- 5. U.S. Department of Commerce, <u>Climatic Atlas of the United States</u>, (Washington, D.C.: GPO, June 1968), Reprint: 1983, National Oceanic and Atmospheric Administration.
- 6. J. T. Kidd, <u>Areal Geology of Jefferson County</u>, (Geological Survey of Alabama, Atlas 15, 1979).
- 7. U.S. Geological Survey, 7.5 minute series Topographic Quadrangle Maps of Alabama, <u>Concord</u> 1979; <u>Bessemer</u> 1959 (Photorevised 1970 and 1978), <u>Birmingham South</u> 1959 (Photorevised 1970 and 1978), <u>Greenwood</u> 1959 (Photorevised 1978).
- 8. NUS Corporation, April 26, 1988. Field Logbook No. F4-814 for Reconnaissance of Hayes International Corporation, TDD No. F4-8804-48.
- 9. George Edwards, Vailhala Cemetary, telephone conversation with Bob Tolford, NUS Corporation, December 15, 1988. Subject: Recreational use of Valley Creek.

Mr. A. R. Hanke Environmental Protection Agency TDD No. F4-8811-20 March 2, 1989 - page two

within these tectonically altered rock units (Ref. 4). Recharge to groundwater is by percolation of precipitation. Net annual rainfall for the area is 11 inches (Ref. 5).

Geologic units that occur within a 4-mile radius of the site, in descending order include: the Parkwood Formation, the Floyd Shale; the Hartselle Sandstone; the Pride Mountain Formation; the Tuscambia Limestone, Fort Payne Chert, and Maury Formation; the Chattanooga Shale and Frog Mountain Sandstone; the Red Mountain Formation; the Chickamauga Limestone; the Attalla Chert Conglomerate Member of the Chickamauga Limestone; the Knox Group undifferentiated, the Ketona Dolomite, and the Conasauga Formation (Ref. 6, Maps 19, 20, 26). Together, these units represent an aggregate thickness of over 10,000 feet of sediment. The presence and thickness of any particular rock unit is dependent on its location within this complex structural setting. Extensive faulting and folding has exposed at land surface the previously mentioned formations (Ref. 3, pp. 7-13). This structural complexity differs from the traditional "layer cake" concept of aquifer and confining layer. These aquifers are unconfined at the surficial outcrop, but may be confined at depth (Ref. 3, pp. 18, 19).

If any groundwater supplies in Jefferson County are used, they are primarily derived from rock units having well-developed water-bearing solution and structural features. Within a 4-mile radius of the facility, the Fort Payne Chert, Tuscambia Limestone aquifer and the Bangor Limestone aquifer are considered to have the greatest potential for development as a groundwater resource. These aquifers currently sustain large volume production wells with yields of greater than 150 gpm (Ref. 3, pp. 41, 42). However, these aquifers are not present in the immediate vicinity of the facility (Ref. 6, Maps 13, 14, 20, 21).

The water-bearing rock units underlying the facility are contained within the outcropping Conasauga Formation (Ref. 6, Map 20). The Conasauga Formation is considered to be a good aquifer in the area, and consists of thinly-bedded brownish-gray sublithographic limestone, gray shale, and brownish-gray dolomite (Refs. 4, pp. 96, 97; 6, p. 3). The beds within this formation dip steeply and contain well-developed solution features capable of producing large quantities of water (Ref. 4, pp. 96, 97). Groundwater from the Conasauga Formation occurs at variable depth from surficial springs to wells 600 feet deep (Ref. 3, pp. 60-75).

Surface water runoff from the site would be via two streams that flow to the northwest into Valley Creek. One stream transects the southwest end of the facility property, the other stream is located about 1000 feet northeast of the northeast end of the property (Ref. 7). There are no surface water intakes within 15 miles downstream of the facility (Ref. 8). Valley Creek is not used for fishing (Ref. 9).

Bessemer purchases water from Birmingham, which services the majority of Jefferson County. Birmingham obtains its water from four sources that do not receive drainage from the facility. The intakes are on the Cahaba River (intake is at Elmore Lake, if level is too low, water is drawn from Lake Purdy), Smith Lake (located in Walker County), and Inland Lake (located in Blount County) (Ref. 8). There are no drinking water wells within a 4-mile radius of Pullman Standard.

Mr. A. R. Hanke Environmental Protection Agency TDD No. F4-8811-20 March 2, 1989 - page three

Based on the above-referenced information and enclosures, FIT 4 recommends that no further remedial action be planned for this facility.

Very truly yours,		Approved:
Poly Talkel		
Bob Tolford		Dety. Blackery
Project Manager		
BT/kw		
Enclosures		
cc:	. EPA PO	

REF. 1

POTENTIAL HAZARDOUS WASTE SITL PRELIMINARY ASSESSMENT EPS FORM 3012-II

TELEPHONE LOG SHEET

1. Site Identification:
Site number: ALD004027729
Site name: Pullman Standard, Division of Pullman Inc.
rathen standard, prototon or rathen me.
2. Interview Data: (Party called)
Name: Hugh Bryant
Position: Plant Manager
Firm: Pullman Stan d ard
Address: 5th Ave. and 24 th St.
Bessemer, Al. 35020
Telephone No.: (205) 425-3240
3. EPS Analyst Data:
Name: Donafiea Dinsmore
Purpose of call: Investigate past disposal activities, confirm current
status
Form 2070-12 (7-81) P.N.
Date of call: 9-10-84
4. Interview Narrative Summary: Pullman is mow a division of Trinity Industries. They
hape to operate under the Pullman name and will be operated locally. They are involved
in fabricating steel. The main waste was from the painting of the railcars. During the
last tem years of operations, waste materials were kept on-site and when the plant
closed, all materials were removed as hase been indicated. Before that time the paint was
hauled off-site and he believes that it was burned. During the mid 1960's they built a
building to house the painting operations. At that time he believes taht they began to
use the Toluene and xylene. The re-usable stencils had to be cleaned when they got
clogged. Before that time, the painting operations were done outside. To the best of
his knowlege, there has been no- on-site disopsal of hazardous materials. When questioned
about the listing of the cresols on the partA application, he was unaware that this
had ever been used.
(He indicated that the paint waste was only hauled off every 5-6 years.)
5. Disposition/Comments:
No furthere action at this site at this time. There has been no on-site disposal of
materials to the best of their knowlege and when they ceased operations in 1980 they
did do extensive cleaning to remove any remaining waste materials and comply with
the RCRA regulations.
Commanders Same additional aiban ward but this assessed
5Comments: Any additional sites used by this company?
Location: Local landfulls
Dates of use: 1929-1970
Description of waste: paant waste and solvents
Comments: Athough this was not specifically indicated during the interview, the
reviewer believes that use of the local landfulls was a definite pessibility. The company
operated for many years before the regulations and landfilling was common.
· Control of the cont

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT EPS FORM 3012-III

INDUSTRIAL NARRATIVE SHEET

1. Site Identification:

Site number: ALD004027729

Site name: Pullman Standard, Division of Pullman Inc.

Site county: Jefferson

2. Industrial Narrative Summary:

Company Name: Pullman Standard, Division of Pullman Inc.

Address: 5th Avenue and 24th Street

Bessemer, AL 35020

Telephone No.: 205/425-3240

Contact: Hugh Bryant

Discussion: Pullman Standard fabricates steel in the production of railcars. In this process they are involved in welding, riveting, bolting, shot blasting, and painting. Their waste products include waste paint as well as the solvents toluene and xylene. This facility closed during 1980 and at that time, they spent both time and money to remove all the remaining waste products from the site. They did not withdraw from interim status in the hope they would be able to reopen or be bought out. In late 1983, they were purchased by Trinity Industries of Dallas, Texas, and operations have resumed as of September 1, 1984. At this time they hope to operate under the Pullman name and remain a division of Trinity Indust. They will operate as a generator only.

For approximately 10 years prior to ceasing operations, waste materials were kept in drums at the site. Waste paints that were left over were kept in the original drum and placed in their yard. Before that time, waste paint materials were hauled from the site every 5-6 years. The company representative believed that the materials were burned. Before the mid 1960's, the painting operations were done outside and they did not use a great deal of solvents. In or around 1965, they built a building to house the painting operations and at that time they began using more solvents to clean the reusable stencils when they got clogged. Disposal of these materials is

uncertain. To the best of knowledge, there has been no on-site disposal of hazardous waste.

Withdrawal from interim status has been requested and granted. Before being allowed to withdraw from interim status, a representative from ADEM visited the site and evaluted the cleanup operations. At that time, they found the site to be clean with no evidence of any on-site disposal or unregulated areas.

3. Disposition:


No further action required at this site under this program. To their best knowledge, there has been no on-site disposal of hazardous wastes at this site and all remaining wastes were removed from the site when they closed in 1980. The company has withdrawn from interim status and has reopened recently under new ownership. They will be regulated as a generator only by ADEM.

4. Comments:

Specific information about disposal of the wastes was unavailable at this time. This reviewer believes that the potential exists that these waste materials were taken to local landfills in operation during the time period this company operated.

REF.2

NUS CORPORATION AND SUBSIDIARIES		TELECON NOTE		
CONTROL NO.	DATE: December 12, 1988	TIME: 08:45		
DISTRIBUTION:				
BETWEEN: Joe Downey	OF: ADEM	PHONE: (205) 271-7700		
AND: Bob Tolford, NUS Corpo	ration Bol Holel			
DISCUSSION:				
which has withdrawn their p		so said that Crown Crentral Petroelum		
ACTION ITEMS:				



ronmental Science Services Administration . Environmental D

Reference #7

OVERSIZED

DOCUMENT

MAP

Rete in the Rain!

LEVEL

NOTEBOOK NO. 311

F4-	- 814	: 1.
		A REF
	Hoyes Internation 54-8804-48	o
	1943 North 50th 5	*
:	Birmingham, AL	
		A. C.
	Dangho M. Charl	63
		The second State of

a product of

J. L. DARLING CORPORATION TACOMA, WASHINGTON 98421 U.S.A.

COSSIN Simmighan derivers the 4-25-88 \$300 p.m. EDT majority of Jefferson Courty. - They do not service Traville Met with warre walker of Fordale, Leeds, er Romas Valler. the franciale littles Company They sell water to Grander le. pondale has 4 wells located Birmingham also salls water to close to the city half. The well Bessene and Bessenes then detho are: #1 is 110 feet, sello to Pleasa & Grove Burningram # 2 2 110 feet, # 4 in 300 ket, serves Terrant and Gardendale and # 5 is 300 feet, frontale also. These man be some Derver approximately 3000 people shirate well is the New selled Their Concease area is primarily within the chafy and Robbins area Left natur dept. at 2:55 p.m. EDT. limits however they do have some lines part the city lin Braingham verves the immedi surrounding were around Ironale Left water desertine. at 3:30 p.m. frondale did not have a city mass available. D.M. (Vatham) 4-16.88 1.M. Chatham 4-26-88

REF. 9

NUS CORPORATION AND SU	NUS CORPORATION AND SUBSIDIARIES				
CONTROL NO.	DATE: December 15, 1988	TIME: 14:15			
DISTRIBUTION:	·				
BETWEEN: George Edwards	OF: Valhalla Cemetary	PHONE: (205) 428-5331			
AND: Bob Tolford, NUS Corporat	tion				
it is not, that local people considuaters were reddish color.	alley Creek. I aksed Mr. Edwards if Vall der the water too polluted, although i	ley Creek is used for fishing. He said that t was much worse years ago, when the			
ACTION ITEMS:					

RCRA/NPL POLICY QUESTIONNAIRE FOR INITIAL SCREENING

Site Name: Pul mon Standar	
City: <u>bessemer</u>	State: Alabama
EPA I.D. Number: ALD ac401773	<u>1</u>
Type of Facility: Generator X Treatment	Transporter Disposal Storage (more than 90 days)
I. RCRA APPLICABILITY	yes no
Has this facility treated, of a RCRA hazardous waste	
Has a RCRA Facility Assessment on this site?	ment (RFA) been performed
Does the facility have a Repermit? If so, date issued	CRA operating or post-closure ×
Did the facility file a RCI	RA Part A application?
 Does the facility control Did the facility with 	urrently have interim status? thdraw its interim status? * nown or possible protective *
Is the facility a late (af- non-filer that has been ide the State?	
STOP HERE IF ALL ANSWERS	S TO QUESTIONS IN SECTION I ARE NO
II. FINANCIAL STATUS	
Is the facility owned by a filed for bankruptcy under laws?	
III. RCRA ENFORCEMENT STATUS	
Has the facility lost author or had its interim status	
Has the facility been invo enforcement action?	lved in any other RCRA

RECONNAISSANCE CHECKLIST FOR HRSZ CONCERNS

Instructions: Obtain as much "up front" information as possible prior to conducting fieldwork. Complete the form in as much detail as you can, providing attachments as necessary. Cite the source for all information obtained.

Site name: Pullman

Pullman Standard

City, County, State: Bosseiner, Jefferson, Alexand

EPAID No.: PREDEODIFICO 43 ES ALDO 0 4017729

Person responsible for form: Bob To I for &

Date: 11/22/38

Air Pathway

Describe any potential air emission sources onsite: none noted

Identify any sensitive environments within 4 miles: none noted

Identify the maximally exposed individual (nearest residence or regularly occupied building - workers do count): workers atsite

Groundwater Pathway

Identify any areas of karst terrain: MA

Identify additional population due to consideration of wells completed in overlying equifers to the AOC: Na = Na

Do significant targets exist between 3 and 4 miles from the site? $-r\,\phi$

Is the AOC a sole source aquifer according to Safe Drinking Water Act? (i.e. is the site located in Dade, Broward, Volusia, Putnam, or Flager County, Florida)

Surface Water Pathway

Are there intakes located on the extended 15-mile migration pathway? No

Are there recreational areas, sensitive environments, or human food chain targets (fisheries) along the extended pathway?

Onsite Exposure Pathway

Is there waste or contaminated soil onsite at 2 feet below land surface or higher? wilknown

Is the site accessible to non-employees (workers do not count)? No, site is fenced with chain link + harbed wive

Are there residences, schools, or daycare centers onsite or in close proximity? Yes . Dunbar High School is less . Dunbar high School is less . Hove School is less . Then 1000 SE of the Site.

SHOTARD RANKLING STOTEM SCORING SUMMARY

FOR

PELLMAN STANDARD

EPA SITE NUMBER ALDCO4017729

BESSEMER

JEFFERSON COUNTY, AL

EPA REGION: 4

SCORE STATUS: IN PREPARATION

SCORED BY BOB TOLFORD OF N U S ON 12/08/SS

DATE OF THIS REPORT: 03/01/89
DATE OF LAST MODIFICATION: 03/01/89

GROUND WATER ROUTE SCORE: 3.47
SURFACE WATER ROUTE SCORE: 2.38
AIR ROUTE SCORE: 0.00
MIGRATION SCORE: 2.43

HRS GROUND WATER ROUTE SCORE

	CATEGORY/FACTOR	RAW DATA	ASN. VALUE	SCORE
1	OBSERVED RELEASE	NO	()	0
₽.	ROUTE CHARACTERISTICS		HEROTER COMMUNICATION AND AND AN ARCHITECTURE	
	DEFTH TO WATER TABLE DEPTH TO BOTTOM OF WASTE	20 FEET 0 FEET		
	DEPTH TO AUUIFER OF CONCERN	20 FEET	2	5
	PRECIPITATION EVAPORATION	53.0 INCHE 43.0 INCH	 -	
	NET PRECIPITATION	10.0 INCH	es e	2
	PERMEABILITY	1.0X10-3 CM/SE	ec a	2
	PHYSICAL STATE		3	3
	TOTAL ROUTE CHARACTERISTICS S	BCORE:		13
3.	CONTAINMENT		3	3
4.	WASTE CHARACTERISTICS			
	TOXICITY/PERSISTENCE:TOLUENE			ę
	WASTE QUANTITY CUBIC YDS DRUMS GALLONS TONS	0 0 9999999 0		
	TOTAL	50000 CU. Y	/DS 8	8
	TOTAL WASTE CHARACTERISTICS S	CORE:		17
5.	TAFGETS			
	GROUND WATER USE		1	
	DISTANCE TO NEAREST WELL	> 3 MILES		. .
	AND TOTAL POPULATION SERVED NUMBER OF HOUSES NUMBER OF PERSONS NUMBER OF CONNECTIONS NUMBER OF IRRIGATED ACRES	MATRIX VALUE O PERSO O O O	O O	0
	TOTAL TARGETS SCORE:			3
	GROUND WATER ROUT	E SCORE (Sgw) =	3,47	

HRS SURFACE WATER ROUTE SCORE

1.	And which the property of the		RAW DATA AS			SCOPE
	OBSERVED RELEASE		NO		0	0
0 ,	ROUTE CHARACTER	ISTICS				
F	SITE LOCATED IN SITE WITHIN CLO FACILITY SLOPE INTERVENING SLO	BED BASIN	NO NO 1.0 1.0		0	U
ć	24-HOUR RAINFALL		4.5	INCHES	3	3
	DISTANCE TO DOW	N-SLOPE WATER	1000	FEET	2	4
ŀ	PHYSICAL STATE			3		3
	TOTAL ROUTE CHAI	RACTERISTICS SC	ORE:			10
3.	CONTAINMENT		*** - 2.07 - 2.07 - 2.07 - 2.07 - 3.07	3		3
4,	WASTE CHARACTER	ISTICS				
	TOXICITY/PERSIS			9		
\$	WASTE QUANTITY	CUBIC YDS DRUMS GALLONS TONS	0 999 9999 0			
		TOTAL	50000	CU. YDS	8	3
ij	TOTAL WASTE CHAP	RACTERISTICS SC	ORE:			17
5.	TARGETS				**************************************	en anthomistre e e e e e e e e e e e e e e e e e e
Č	BURFACE WATER US	BE			1	3
Ĭ	DISTANCE TO SEN COASTAL WETLA FRESH-WATER V CRITICAL HABI	ANDS VETLANDS	ENTS NONE NONE NONE		0	c
I	DISTANCE TO STATE DISTANCE TO WATE AND FOTAL POPULATION NUMBER OF HOLE NUMBER OF PER NUMBER OF COME NUMBER OF IRF	R SUPPLY INTAK 1 SERVED JSES JSONS JNECTIONS			0	0
	TOTAL TARGETS SO	OGRE:				T

HRS AIR ROUTE SCORE

	CATEGORY/FACTOR	RAW DATA	ASN. VALUE	SCORE
1	OBSERVED RELEASE	NO	0	0

2. WASTE CHARACTERISTICS

REACTIVITY:

INCOMPATIBILITY

and Managard and the first of the Ambuta ham the first

TOXICITY

WASTE QUANTITY CUBIC YARDS

ORUMS GALLONS TONS

TOTAL

TOTAL WASTE CHARACTERISTICS SCORE:

NZA

MATRIX VALUE

S. TARGETS

POPULATION WITHIN 4-MILE RADIUS

O to 0.25 mile

O to 0.50 mile

0 to 1.0 mile

O to 4.0 miles

DISTANCE TO SENSITIVE ENVIRONMENTS COASTAL WETLANDS FRESH-WATER WETLANDS CRITICAL HABITAT

DISTANCE TO LAND USES
COMMERCIAL/INDUSTRIAL
PARK/FOREST/RESIDENTIAL
AGRICULTURAL LAND
PRIME FARMLAND
HISTORIC SITE WITHIN VIEW?

TOTAL TARGETS SCORE:

N/A

AIR ROUTE SCORE (Sa) = 0.00



Site Inspection Report

POTENTIAL HAZARDOUS WASTE SITE

I. IDENTIFICATION

GEPA	PART 1 - SIT	SITE INSPE	ction report No inspection impor	1 4 1	4004017729
II. SITE NAME AND LOCATIO					
Pullman Stando			5th Ave	and 24 th 5	·
3 CTY	2100		ON STATE OF 25 COOK	OR COUNTY	0700UNT 18 00MG
Dessemer seconomines		1-0 TYPE OF GWAR	AL 35020	Je ferson	
37 34 40.0 U	36 36 40.1	P OTHER	T I PEDERAL	_ I C STATE I D COUNT	Y I E MUNICIPAL
IN INSPECTION INFORMATION OF DATE OF REPECTION	102 STE STATUS	03 YEAR OF GIR			
12 1 88 100174 34 - 1888	SAGRE AUT ENACTIVE	fre-mid	603 1980	UNKNOW	N
CA ADDICY PERCALING MAPECTI CA EPA XI EPA CONTI		CUTP.	_ C. MUNICIPAL C.D.	MUNICIPAL CONTRACTOR	
SE STATE OF STATECON		W/W	_ C @ OTHER	Specific	1976 3 mm
K.D. Pass		OS TITUE		NUS CUIP	08 TELEPHONE HO 140+1 935-7710
OF OTHER REPECTORS		10 7774		11 OF ANELATION	12 TELEPHONE NO
Bob Tolferd			Technicion	NUS	1404 1 938-7710
Lorry Grie	er	Field T	echnicion	NU5	14041 938-7710
, , , , , , , , , , , , , , , , , , ,			-		()
					()
					()
None	hve)	14 1114	14400000		18 PELEPHONE NO
					()
					()
					()
				transfer of the second of the	()
	9 5-7		·		()
	÷				
7 ACCOUNT CANDO OF THE TOTAL CONTROL OF THE TOTAL C		10 WEARINGS	unny		
V. BEFORMATION AVAILABL	E Photal				(SE FELST-KINE NO.
Bob Tolford	on KD. Pass	1005			1404) 938-7710
Bob Tolfor	NO CONTROL OF THE PARTY OF THE	NUS	OF CHEMICATOR	(404) 938-7710	12 15 38

POTENTIAL HAZARDOUS WASTE SITE

I. IDENTIFICATION

OF	PA		SITE INSPECTION REPORT PART 2 · WASTE INFORMATION		AL DOOR	AL DOUGOI 7729	
II. WASTE	TATES, QUANTITIES, AN	O CHARACTER	STICS				
	STATES CHARGE COM	02 WASTE GUART	TV AT SITE	03 WASTE CHARACT	ERETICS (Chap at the se	NOV.	
I A SOUD I B POWO I S SLUCK	en mass XV ugund	TONS -	Nine present	C A TOXIC C B CORRC C C RADIO C O PERMI	STIVE SIG PLANS	AGLE IN PLACE	M
2 o orher		NO OF OPUMS				E M YOT M	PLCABLE .
III. WASTE		-		<u> </u>			
CATEGORY	SUBSTANCE N	AND	01 00000 440100	DE UNIT OF MEASURE	10200000		
SLU	SLUDGE				, www		
OLW	OILY WASTE				<u> </u>		
501	SOLVENTS						
P90	PESTICIDES						
occ	OTHER ORGANIC CH	EMICALS					
ЮC	NORGANIC CHEMIC	N.S					
400	ACIOS						
848	EASES						
WES.	HEAVY METALS						
IV. HAZARO	OUS SUSSTANCES (See As		and CAS Tempers				
OI CATOCORY	02 SUBSTANCE NA	and .	OS CAS HARRIST	04 STORMSEON	POBAL METHOD	06 CONCENTRATION	254
SOL	Toluene		106-38-3		eled off and	unkhann	
SOL	Kylene		1330-20-7	drum/Possi	ly burned	unkanh	
	·						
							L
		Ü					
							<u> </u>
V. PERDETO	CKS des Apparents des						
CATEGORY		Media	-	CATEGORY	01 / 10000100	M NAME	OR CAR MUNICIPA
P04				F00			
F08				700	ا ۱ سال ما النبي بسنم بسن سند به مساو		
FDS				700			
P06				706			
A SOURCE	OF INFORMATION and		والمراجع المراجع المرا				
potentia	1 Huzardous Waste	Site prelimin	wry Assess in	ent form (E	15 Form 3012-111) for Auliman sy	onelisi (

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

1. IDENTIFICATION

01 STATE 32 STE NUMBER

A L 0 00401-7729

PART J - DESCRIPTION OF	HAZARDOUS CONDITIONS AND INCIDES	ITS COMMENT	70 701 71 74
II. HAZARDOUS CONDITIONS AND INCIDENTS			
31 TA GROUNOWATER CONTAMINATION 33 POPULATION POTENTIALLY APPECTED: None	02 C COMPINED (DATE:) 04 MARRATIVE DESCRIPTION	- POTENTIAL	= ALLEGED
population served by sur	rface water		
31 28 SURFACE WATER CONTAMINATION None	02 = OBSERVED (DATE	= POTENTIAL	2 ALLEGED
surface water supplies are	e not within the 15 mile p	onth was.	
G1 = C CONTAMENATION OF AIR 03 POPULATION POTENTIALLY AFFECTED: More	02 T DESERVED (DATE) 04 NARRATIVE DESCRIPTION	S POTENTIAL	S ALLEGED
01 = 0. FREEDRICENE CONSTITUTE OF POPULATION POTENTIALLY AFFECTED: None Wistes were personed in	03 C CRESTIVED (DATE) 04 MARKATIVE DESCRIPTION 1980.	З РОТВИТАL	2 ALEGEO
01 = E DIRECT CONTACT 03 POPULATION POTENTIALLY APPECTED: Mone	DE CI COMMINIO (DATE:) DE NASSATIVE DESCRIPTION	S POTENTIAL	I ALLEGED
01 T F CONTAMENATION OF SOIL	OF C COMMINS (DATE)	& FORDINAL	I ALLEGED
01 of CONTAMENTON OF SOL	contamination may or may no	, -	
a The stage of the	,		
01 C.Q. OFFICE WATER CONTINUENTION NOTE 03 POPULATION POTENTIALLY AFFECTED NOTE	OR CI CONSTINED (DATE:) 04 NAVINATIVE SEECRETION	C POTENTAL	CROBLIA C
OI CH. WORKER CONTROLLEY			- W 605D
workers may have been aff	exted during operations prior to	1980 when offi	nation, revocal.
01 CL POPULATION OF CHURENAUTY DONE VOICE	02 C COSSIMED (DATE) 04 MARKATINE DESCRIPTION	G POTENTAL	C ALLEGED

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

L DENTIFICATION
OF STATE OF STE MARKET

PART J-DESCR	INFICITOR OF MAZARDOUS CONDITIONS AND INCIDENTS	1/2	0004017774
IL HAZAROOUS CONDITIONS AND INCIDEN	ITS Communication		
OT I DAMAGE TO FLORA	02 C OBSERVED (DATE.	3 POTENTIAL	I ALLEGED
04 NARRATIVE DESCRIPTION	observed, visual access to sto	rouge area	workental
are to size of overall for	cility	- Je wrea	prevon ex
and to size of over	c., ().		
D1 I 4 JAMAGE TO FAUNA	02 I OGGERVED IDATE		
34 NARRATIVE DESCRIPTION Inches remain of teatre	W C2 _ CEMENTED (DATE)	POTENTIAL	I ALLEGED
ditto			
Ū			
1 T L CONTAMNATION OF FOOD CHAIN 4 NARRATIVE DESCRIPTION	02 C OGGETVED (DATE)	I POTENTIAL	I ALLEGED
None			
,			
1 Z M. UNSTABLE CONTAINMENT OF WASTES	02 C 0000FWED (DATE:)	= POTENTIAL	- ALEGED
POPULATION POTENTIALLY APPECTED: 1/3	O4 NATURATIVE DESCRIPTION		
No wastes	are sent		
No worker			
1 = N DAMAGE TO OFFSITE PROPERTY	02 C CESETIVED (DATE:)	= POTENTIAL	S ALLEGED
MARRATINE DESCRIPTION			- ~L
/ 0	1/12		
I _ 0. CONTAMINATION OF SEWERS, STORM D I NAMINATIVE DESCRIPTION	DRANG, WWTPs DE C CREETVED (DATE:)	C POTENTAL	I ALLEGED
1/02e			
1,70,			
T P ILLEGAL/MAUTHORIZED DUMPNIS	OR CI CORRESPOND (DATE:)	C POTENTAL	3 ALLEGED
(
Unknown	Antiger of the second of the s		
DESCRIPTION OF ANY OTHER ISLOUIS, POTE	WINL OR ALLESSE HAZARDS		
unknoun			
Chinoch	est Art - € en est en		
•			
TOTAL POPULATION POTENTIALLY APPR	The Nor		
COMMENTS			
•			
SOURCES OF REPORMATION AND ADDRESS AND	THE R. P. LEWIS COLUMN		- 2 /
Potential Hazardous Waste Site Pr	eliminary 4 seasonant form (EHS Form 3012-111) for	Full mon STa	nous

SEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION PART 4 - PERMIT AND DESCRIPTIVE INFORMATION

1. IDENTIFICATION
01 STATE 02 SITE NUMBER
AL 1004017729

II. PERMIT INFORMATION 21 THE OF SERVICE SALED CONTROL OF SERVICE CONTROL	ATION	AL MO04017779
TA MODES TO NOTE TO NOTE TO AND TO		
TO ARE TO ARE TO AREA TO AR	B 06 COMMENTS	
TO ARE TO ARE TO AREA TO AR	f	
TO A PAGE AND A PAGE A	witholicen	w part B BT
TO A CONTAINMENT		
Z STATE SEARCY Z STATE SEARCY Z H LOCAL SEARCY Z J NONE L STTE DESCRIPTION 1 STORAGE DEPOSAL CASE OF MY MANY Z A RUBBARATION Z A RU	withdraw	furt B
SOURCES OF INFORMATION OF MALES AND ASSETS MALES OF PROCESSION OF PROCES		
EN COCAL SECTION ESTRE DESCRIPTION STORAGE DESCRIPTION STORAGE DESCRIPTION TO A SUPERACE EMPOLNOMENT E PLES SC DELME ABOVE GROUND E TANK RELOW GROUND E TANK RELOW GROUND C I AND ABOVE GROUND C I AND ABOVE GROUND C I COTHOR SOUTH TRECOVER C I COTHOR C I C I COTHOR C I C I COTHOR C I C I C I C I C I C I C I C I C I C		
E. OTHER SECRET ON STORAGE DESCRIPTION STORAGE DESCRIPTION THE A SUFFACE MEDIUM MENT THE BEST OF MARCH ADDRESS OF MEDIUM THE A SUFFACE MEDIUM MENT THE BEST OF MARCH ADDRESS OF MEDIUM THE A SUFFACE MEDIUM OF THE MENT THE ADDRESS OF MEDIUM THE A		
ESTE DESCRIPTION STORAGE DESCRIPTION STORAGE DESCRIPTION STORAGE DESCRIPTION STORAGE DESCRIPTION A RECERCITION C. A. ADECURATED CONTROL LATERUM CONTROL	<u> </u>	
LETTE DESCRIPTION STORAGE DEPORAL COME OF MANDERS A SURFACE INFOUNDMENT S. PLUS S. COMMANDATE ABOVE GROUND LYNKINGH G. CHARLABOVE GROUND LYNKINGH G. CHARLABOVE GROUND S. LINGSTORAGE DEPORMATION G. COMMANDATE G. COMMANDAT		
STORAGE DEPOSAL CHARMENT A SUPPACE MEDIUMOMENT B. FILES C. CHARLA MOVE GROUND LYTKOWN C. O. TANK, ABOVE GROUND LYTKOWN C. O. TANK, ABOVE GROUND C. TANK, ABOVE GROUND C. F. LANDFUL C. LANDFUL C. LANDFUL C. LANDFUL C. LANDFUL C. LANDFUL C. OTHER RESTOLUTE C. OTHER RESTOLU		
CONTAINMENT CONTA		
CONTABINISH CONTA		of other
CONTABOLITY CONTA		TIE NO BONGAUS A C
CONTABBLET CONTAB		
CONTANTANT CONTANTANT CONTANTANT CONTANTANT CONTANTANT CONTANT CONTAN	~	
CONTAINMENT CONTAI	Nervis	OF AREA OF SITE
CONTAINMENT CONTA		210
CONTABILIENT CO		
CONTABILITY OR MASTER LARGE CONTROL OF MASTER C		
CONTINUED OF WASTE COME CONTINUED CONTINUED OF MASTE STATE OF MASTER ASSESSMENT FOR ACCESSION TO OI WASTE EARLY ACCESSION OF PROMINATION OF MASTE STATE OF PROMINATION OF PROMINATION OF PROMINATION OF PROMINATION OF		
CONTINUED OF WASTE COME CONTINUED CONTINUED OF MASTE STATE OF MASTER ASSESSMENT FOR ACCESSION TO OI WASTE EARLY ACCESSION OF PROMINATION OF MASTE STATE OF PROMINATION OF PROMINATION OF PROMINATION OF PROMINATION OF		
ACCESSIONLITY OI WASTE EARLY ACCESSION OF PROMISE OF MASTER OF PROMISE OF PR		
Wester in question are no longer Wester in question are no longer Wester in question are no longer Or waste present Bounces of promision as a serious waste site preliminary Assessment For	C D. MINECUR	E, UNECUNO, SANGEROUS
Wester in question are no longer Wester in question are no longer Wester in question are no longer Or waste present Sources of promision as a serious waste site preliminary Assessment For		
ACCESSION TY OI WASTI EARLY ACCESSION OF WASTE Present No waste present Sounces of Deformation on the manual access of the preliminary Assersment For the present of the	present.	
No Waste Present Bounces of African Annual Hazardous Waste Site Preliminally Assersment Fo		
No waste present Bounces of Aformation and Auguste Site preliminary Assessment Fo		
potential Hazardous Waste Site Preliminary Assersment Fo		
presitual Hazardous Waste Site Preliminuly Assersment Fo		
p teritual Hazardous Weste Site preliminary Assersment Fo		
P. Ul min 5 rondard -	om (Eps For	m 3012-111) for

I. IDENTIFICATION POTENTIAL HAZARDOUS WASTE SITE OI STATE OR STE WOMEN SITE INSPECTION REPORT AL 0004017729 PART 5 - WATER, DEMOGRAPHIC, AND ENVIRONMENTAL DATA II. DAINKING WATER SUPPLY O1 TYPE OF ORDERING SUPPLY Chan to expension 02 STATUS OS CHITANCE TO SITE SUFFACE WELL ENCANGERED AFFECTED MONTORED 4 = COMMUNITY ■. 🗆 A. C 8. 🔾 C. 🗆 c I 0 = YON-COMMUNITY 0. 🗆 L J F 3 -III. GROUNDWATER 31 GROUND ZRUBE N VICINITY Chase and I A ONLY SOURCE FOR DRINKING C COMMERCIAL PRODUCTION NOT USED. UNUSEABLE ERCAL HOUSTRUL PRICATION OS CHETANCE TO MEANEST GROWING WATER WELL MIVE This 4 (m) DE POPULATION SERVED BY GROUND WATER .. OF CONCERN 04 DEFTH TO GROUNDWATER 06 DIRECTION OF GROUNDWATER FLOW 07 POTENTAL TELD 06 SOLE SOURCE AQUIFER C YES INO OR DESCRIPTION OF WELLS remains and A percolation of precipitation, RYES COMMENTS Area has extensive foults + folds O YES COMMENTS CHINO CNO IV. SURFACE WATER OT SURFACE WATER USE COMM ON C A RESERVOIR RECREATION OFFICERS WATER SOURCE G & PREATON SCONOMICALLY MATCHTANT RESOURCES DE D. NOT CURRENTLY USED C C. COMMERCIAL, INDUSTRIAL OR APPRICIONS OF WATER NAME: ACCOUNT DISTANCE TO SITE Valley Creek (478) (#1 BIOGRAPHIC AND PROPERTY REPORT OI TOTAL POPULATION WITHOUT TO A PROPERTY AND ADDRESS OF THE PARTY AND THREE (3) MILES OF SITE ONE (1) MILE OF SITE THO CO MELINOF SITE -0 0 7 4000 03 MARGET OF SULLIVIES WITHIN THE OF SITE ---04 DISTANCE TO HEAR mony, its on whom when OI POPULATION WITHOUT VICENTY OF STE phonos nations examples of square of properties with making of ste, e.g., stee, steeps are

SEPA

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PARTS - WATER, DEMOGRAPHIC, AND EMVIRONMENTAL CO.

١.	DENT	FIFICATION
91	STATE	02 215 ACMBES

AND PARTIES OF THE PA	PARTS WATER, DEMOGRA	PHIC. AND ENVI	RONMENTAL	DATA L	COS 315 ACMOS
VI. ENVIRONMENTAL INFORMATIC 31 PERMEAULY OF JANAGARED COME	3 4				
= 4 10-4 = 10-4 m	NAC - 7 8 1004 - 1004 - 10	`			
	Nees ,C 8. 10-4 - 10-4 crivees	XC . 10-4 - 10-3	PROPERTY CO. G.	REATER THAN	10-3 anvecs
A SECURE OF THE SECURE CHES SAN					
A MPERMEAL	ILE I B. RELATIVELY IMPERMENT	WE PELATIN	ELY PERMEABLE	E I O VERV	
JEPTH TO MEDROCK 1447	DEPTH OF CONTAMINATED SOIL ZONE		- 4 SWeek)	Green	Man 10 " Der tool
Fault - Zone, coall be	LIAL LUCA	38 SOL			
	unknown	i,	ukhown		
970	HE FEW 24 HOUR RANGALL	SITE SLOPE	. 0.000.000	<u> </u>	
LOGO POTENTIAL	4,5	1.0	NE	SITE SLOPE	TERRAIN AVERAGE S
-	10				
TEISINYEAR FLOODFL	AIN STEIS ON SARE	MER ISLAND. COAST	AL HIGH HAZARO	AREA, RIVER	NE PLOCOWAY
STANCE TO WETLANDS IS NOT THE PROPERTY.		12 DISTANCE TO CHE			
ESTUARINE	OTHER			- Children Street	
A(mi)	0(m)		_		
O USE ALVICATIV		SIGMOST	D SPECIES:		
DISTANCE TO:					
COMMERCIAL/HOUSTRIAL	PERCENTIAL AREAS: NATION PORESTS, OR WELDLIF	MALISTATE PARKE		A0000 = 0 = 0	
	COMMENTS ON MEDITA	E VERBINER	PROME A	AGRICULTUR GLAND	AGUNO
A () (m)	- 41				
(IVII)	• 	(mi)	C	(min)	o
CAPTION OF SITE IN ABLATION TO SURE	OUNDING TOPOGRAPHY				
• .					
•					
			•		
	 -			•	
*					
INCES OF INFORMATION AND SELECT					
					

&EP#		•	POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT ART 6 - SAMPLE AND FIELD INFORMATION	L CONTIFIC	
E SAMPLES TAI	KEN				
SAMPLE TYPE		SAMPLE TAKEN	02 SAMPLES SENT TO		AS ESTEMPTED OF TE
GROUNOWATE					
SURFACE WATE	ia 				
WASTE -					
AM					
AUNOFF					
5ATT					
504.					
VEGETATION					
OTHER					
IL PILD MEASU	NEMENTS TA				
or five		or contracts			
					
·					
					
IV. PHOTOGRAPH	E AND MARK				
OF TYPE C GROUP			OR IN CASTOSY OF		
J well	04 LOCATION	1			
C YES					
V. OTHER PIELD B	MYA COLLEC	10 ~ · · · · · · · · · · · · · · · · · ·		•	
•					
	•				
		•			
vi. SOURCES OF 1	NPORMATION	1 400 00000 0000000 0	s. also the arrive reduce, record		

&EPA		POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 7 - OWNER INFORMATION			I DENTIFICATION	
IL CURRENT OWNERS		PARTY-ON	PARENT COMPANY			
		02 0+0 MARSER	22 11012	16	0 0 + 0 N. actic A	
Trinity Industries			Trinity Industrie	25		
03 STACE + 24th 51		04 MC COOM	10 STREET ADDRESS P 0 But 400 on 1		11 SEC COOE	
5 Ave + 24- 77	Yee7	TE 07 29 000E	1200 FO. 65 4847	13 STATE	110000	
Bessemer, Alahanza	Ai	35020	palles	1 -1	15356 - 583 7	
I NAME		02 0+8 MUMBER	OB NAME		9 0 + 8 MUMBER	
3 STREET ADDRESS / O dea AFD F are .		04 SC CODE	10 STREET ADDRESS (P.O. Aug. APG.P. aug.)		1 SC CODE	
os arv	06 \$7A7	907 20 COOS	12 017	13 STATE	◆ 21P COO€	
1 NAME		02 0+6 MANGER	OS NAME		9 0+8 MUMBER	
3 STREET ACCRESSIO O BOLL MED F COL.)		04 SEC COOR	10 STREET AGGRESS (# 0. dec. AFD # est.)		11 SIC COOR	
e an	00 STAT	E 07 29 0008	12 OTV	13 87A78 1	12 COM	
1 MAME	L	02 0+6 MANGER	OR NAME		00-0 MANGER	
3 STREET ACCIDEDS IP 0 day APD 0 mg.		04 80 0008	10 STREET ACCRESS # 0 0m #9 0 mil		11 SC COOE	
(a n	GG STAT	FF 29 6584	18 GIV	STATE	4 29 COOE	
IL PREVIOUS OWNERS) AND THE		<u> </u>	N. REALTY OWNERS A			
Pullina Standar	k	00 0+0 10,00007	01 AVAIS		2 D+0 NUMBER	
\$ 5th Ave + 24.	Street	04 85 COM	CO STREET ACCRECATE C ALL MOV. CO.		04 SEC COOE	
lar Besseiner	AI.	35020	a div	OS STATE	7 IP COSE	
TWEE STATE OF THE		21 5 + 1 PARENT	V) NOTE		E D+S HUMBER	
STREET ABSPECES # 6 day 449 A cas		6.8568	00 577007 ASSESSED & 00. APP. 00.		04 SE COOS	
ich .		7 5 CM	SC CHT	S SIATE	7 39 COOR	
- Name		RE SHERWARD	51 1008		2 5+3 HUMBN	
STREET ACCORDED # 6 Res APP.C. doi:		64 85 0004	08 STREET ASSESSED (* 0 cm. 4794. cm.		94 8C COOR	
IGN	es d'Al	# 2000s	os arv	STATE S	7 29 0004	
. SOURCES OF REFORMATION A						
		44. mgs 616. cartes order				

&EPA	SITE	HAZARDOUS WASTE SITE NSPECTION REPORT	I. IDENTIF	GATION SITE MUMBER
	PART 4 - 0	OPERATOR INFORMATION	<u> </u>	
H. CURRENT OPERATOR	equal .	OPERATOR'S PARENT COMPA	WY	
Trinity Industries	02 0+0 MJA#	Trinty Industrie	5	110+814,44831
511 Ave + 24th street	04 9 € 00	P.O. Pox 968887		13 SIC COOE
Bissamer.	A 5620	pallas, TX.	15 STATE	19396 - 5897
08 YEARS OF OPERATION DO NAME OF OWNER				
M. PREVIOUS OPERATOR(S) Les mes mess tre				
Pullmon 5ton bank	02 0+0 MJAME 04 SEC COS			1 D+@ NUMBER
5th Ave + 24th street	-			13 SIC COOE
Jesse Mer	41. 35020	14 GiTV	16 STATE	16 IP COOE
1 RAAM	SE S+ B INJAME			1 5+8 MARKET
STREET ACCRESS IP O. Das. APD P. COL.	64 85 600	12 STREET ASSUMES IN A SILL AND A MAN		13 SE COOE
€ GIV	STATE OF SP COOL	14 GIV	18 STATE	8 29 000€
SYEARS OF OPERATION OF MALE OF CHARGE DU	Riving Their Pillering			
	00 0+0 re.hall	141000		1 0+6 NUMBER
5 6774167 AGGP/866 (P G. Sin. APO F, cm.)	A BE COL	12 SHOULD ASSESS FOR the APP.C. CO.	· · · · · · · · · · · · · · · · · · ·	13 50 0006
i div		14 .617	1687410	● 27 0000 €
YEARS OF GROWN TON ON MAKE OF GROWN SE				

SEPA	,		hazardous waste site ISPECTION REPORT	OI STATE OF	SIE YUMBER
AU V	PART		DR/TRANSPORTER INFORMATION		
on-site generator					
NAME .		02 0+8 MUNICER			
STREET ADDRESS # 2 Jan AFD # mg ;		04 900 0000			
3 7	OS STATE	07 29 CODE			
OFF-SITE GENERATORIS)				· ·	
AAAA		02 0+0 N.A.	01 MAKE	(R38MJ# 8 - C S
TREET ADDRESS P 0 Box. 970 F ore;	I	04 SEC COOK	03 STREET ADDRESS .P 0 dec 400 F mt.		34 SIC 000€
יזו	00 STATE	07 20 COO4	os arv	OG STATE	of the code
		02 0+8 NAMES	OT RANK		32 0+6 MUMGER
THE T ACCRESS IP Q. SEL APP F. SEL		04 BC CCCC	00 STREET ADDRESS IP G. das. APD P. co.		04 SEC COOR
~	ON STATE	67 29 CODE	os arry	OS STATE)7 3 000s
TRANSPORTER(S)					
		OE D+ & HUMBER	01 MANS		REDMUM B+0 SC
THEET ACCRESS IP Q. Sen. AND F. sen.)		64 62 000	OS STREET ACRESSE IP Q. San. 670 F. HAL		04 SIC COOE
₩	OF STATE	07 2F 0008	os carry	OB STATE	7 2P COOS
wid		N S+6 MARCH	81 NAME		De Des MANSER
THE T ADDRESS IF & SEL IFFS (. 164)		N 815 005E	45 STREET ASSESSED (* 8. am. 449 /. am.)		04 SEC CODE
N	00 Grand	v bau	ss cerv	OL STATE	17 20 COOL
	1 1				

^	
4	

POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 10 - PART RESPONSE ACTIVITIES

ŧ,	DON		CAT	104	
1	STATE	03	ži į	-	

VUA	PART 10 - PAST RESPONSE ACTIVITIES		
& PAST RESPONSE ACTIVITIES			
01 C A. WATER SUPPLY CLOSED	02 DATE	03 AGENCY	
01 2 8 TEMPORARY WATER SUPPLY PROVID 04 DESCRIPTION	DED 02 DATE	OJ AGENCY	
01 2 PERMANENT WATER SUPPLY PROVID 04 DESCRIPTION	© 02 DATE	OJ AGENCY	
01 5 0. SPELED MATERIAL REMOVED 04 DESCRIPTION	OZ DATE	03 AGENCY	
01 T. E. CONTAMBIATED SOIL REMOVED 04 DESCRIPTION	02 DATE	03 AGENCY	
01 C F WASTE REPACKAGED 04 DESCRIPTION	02 DATE	03 AGENCY	
O1 C G. WASTE DISPOSED GLIEWINGTE O4 DESCRIPTION	02 CATE	OS ASSIVEY	
01 C H. ON SITE BURNAL 04 DESCRIPTION	OZ GATE	OS ASSECT	
01 (2). IN SITU CHEMICAL TREATMENT 04 DESCRIPTION	OE DATE	03 AGENCY	
Q1 (2 J. IN SITU SIGLOGICAL TREATMENT 04 DESCRIPTION	OE DATE	03 AGENCY	
01 C K. IN SITU PHYSICAL TREATMENT 04 DESCRIPTION	06 DATE	09 ACCOUNTY	
01 C L BICAPELLATION 04 DESCRIPTION		MARCY.	
01 C M. BASTABACY VANDE THEATERN 04 DESCRIPTION	OE CAPE	OS ANDREY	
01 C N. CUTOFF WILLS 04 OBSCRIPTION	CE DATE	03 A684CY .	
01 C O. EMPROPICY CHINE-BUFFACE WATER 04 DESCRIPTION	DIVERSION OS DATE	OS ASSIST .	
01 C P CUTOFF TRENCHES BLASP 04 DESCRIPTION	OZ DATE	OS AGENCY	
01 C Q. SUBBLIFFACE CUTOFF WALL 04 DESCRIPTION	OZ DATE	OS AGENCY	

&EPA	POTENTIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT PART 10 - PAST RESPONSE ACTIVITIES		I. IDENTIFICATION
PAST RESPONSE ACTIVITIES Comment			
C1 TR BARNER WALLS CONSTRUCTED 04 DESCRIPTION	02 QATE	03 AGENCY	***************************************
31 2 S CAPPING COVERING 34 DESCRIPTION	02 0ATE	03 AQUACY	
OI ST BULK TANKAGE REPARED 04 CLUCRATION	02 DATE	03 AQBICY	
01 T J GROUT CURTAIN CONSTRUCTED 04 DESCRIPTION	OZ DATE	03 AGENCY	
01 I V BOTTOM SEALED 04 DESCRIPTION	02 DATE	03 AGENCY	
01 I W GAS CONTROL 04 DESCRIPTION	C2 DATE	03 AGENCY	
01 Z X. PINE CONTROL 04 DESCRIPTION	OE DATE	03 AGENCY	
01 2 Y LEACHATE TREATMENT	GE DATE	00 AGENCY	
01 C Z. AMEA EVACUATED 04 DESCRIPTION	QE DATE	OS AGENCY.	
01 = 1 ACCESS TO SITE RESTRICTED 04 DESCRIPTION	OR DATE	09 AGENCY	
01 C 2. POPULATION RELOCATED 04 DESCRIPTION	OE DATE	OS ASSICY.	
01 C 3. OTHER REMEDIAL ACTIVITIES 04 DESCRIPTION	OF BANK	OS ASSISTA	
	•		•
CURCES OF REPORMATION AND AND ASSESSMENT	1016 A.S. (1827 The series origins report)		



POTENTIAL HAZARDOUS WASTE SITE

	OENT		
31	STATE	OZ SITE YLMBER	

SEPA	SITE INSPECTION PART 11 - ENFORCEMEN	SITE INSPECTION REPORT PART 11 - ENFORCEMENT INFORMATION			
IL ENFORCEMENT INFORMATION					
OI PAST REQUIATORY ENFORCEMENT ACTION					
OF PART REQUIATORY ENGINEERIN ACTION DE DESCRIPTION OF FEDERAL STATE, LOCAL					
12 DESCRIPTION OF PEDENCE STATE, COOK					
		·			
	·				
نيو ۴۰۰					
74	· · · · · · · · · · · · · · · · · · ·	A.	- 		
	**				
·	. •				
L SQUACES OF REFORMATION (Street					
	THE PERSON LAW AND DESCRIPTION ASSESSMENT AS				

POTENTIAL HAZARDOUS WASTE SITLE PRELIMINARY ASSESSMENT EPS FORM 3012-11

TELEPHONE LOG SHEET

1. Site Identification:
Site number: ALD004027729
Site name: Pullman Standard, Division of Pullman Inc.
2. Interview Data: (Party called)
Name: Hugh Bryant
Position: Plant Manager
Firm: Pullman Standard
Address: 5th Ave. and 24 th St.
Bessemer, Al. 35020
Telephone No.: (205) 425-3240
3. EPS Analyst Data:
Name: Donathea Dinsmore
Purpose of call: Investigate past disposal activities, confirm current
status
Form 2070-12 (7-81) P.N.
Date of call: 9-10-84
4. Interview Narrative Summary: Pullman is mow a division of Trinity Industries. They
hape to operate under the Pullman name and will be operated locally. They are involved
in fabricating steel. The main waste was from the painting of the railcars. During the
last tem years of operations, waste materials were kept on-site and when the plant
closed, all materials were removed as hase been indicated. Before that time the paint was
hauled off-site and he believes that it was burned. During the mid 1960's they built a
building to house the painting operations. At that time he believes taht they began to
use the Toluene and xylene. The re-usable stencils had to be cleaned when they got
clogged. Before that time, the painting operations were done outside. To the best of
his knowlege, there has been no- on-site disopsal of hazardous materials. When questioned
about the listing of the cresols on the partA application, he was unaware that this
had even been used
had ever been used.
711 - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
(He indicated that the paint waste was only hauled off every 5-6 years.)
5. Disposition/Comments:
No furthere action at this site at this sime. There has been no on-site disposal of
materials to the best of their knowlege and when they ceased operations in 1980 they
did do extensive cleaning to remove any remaining waste materials and comply with
the RCRA regulations.
the MNA Tegurations.
6. Comments: Any additional sites used by this company?
Location: Local landfulls
Description of waste: paiant waste and solvents
Comments: Athough this was not specifically indicated during the interview, the
reviewer believes that use of the local landfills was a definite pessibility. The company
operated for many years before the regulations and landfilling was common.

ENVIRONMENTAL PROTECTION SYSTEMS, INC. Alabama RCRA 3012 Site Ranking Scheme EPS Form 3012-V

Site Number Pulman Std

Preliminary Assessment Ranking Scheme to Determine Which Sites Merit Further Action.

(Select one answer for each of the following seven questions)

1.	Are Hazardous Substances Present?	
	A. Confirmed on site!	10 points
	B. Suspected at site!	5 points
	C. It is unknown!	2 points
	D. No hazardous substances	O points 🕳
	E. RCRA facility only!	0 points X
_		
2.	Is There a Pollution Dispersal Pathway?	
	A. Direct to surface and/or groundwater.	5 points
	B. Indirect to surface and/or groundwater.	4 points
	C. Suspected to surface and/or groundwater.	3 points
	D. Not known for sure.	2 points
	E. No pathway.	0 points
2		
3.	Characteristics of Human Population?	r
	A. High density.	5 points
	B. Medium density.	4 points
	C. Low density. D. No population.	3 points
	b. No popuración.	2 points
4.	Characteristics of Natural Environment?	
٠.	A. Critical habitat including endangered	
	species, etc.	5 points
	B. Sensitive habitat.	3 points
	C. Common less sensitive habitat.	2 points
5.	How is Human Population Affected By Site?	
	A. Public utility of drinking water	
	from site.	5 points
	B. Direct public access to site.	4 points
	C. Public access to affected	
	surface water.	3 points
	D. Only potential for human	
	population contact.	2 points
	E. Low or no potential for contact.	1 point
c	Capility Management Durations of City	
6.	Facility Management Practices at Site?	
	A. Site actively supervised and managed	
	currently with monitoring reports and	1 maint
	other permit and report requirements.	1 point
	B. Site inadequately managed records	2 mainta
	not up-to-date.	3 points

C. Site not currently managed or regulated. 4 points Abandon site. D. 5 points 7. Potential Responsible Parties for Site Operations? A. Controlling party identified and accepts responsibility for site. 1 point Suspected controlling party identified but does not accept responsibility for site. 4 points C. No responsible party available. 5 points

Ranking Score =

TABLE 1. Ranking Assessment

NUMERICAL RANGE	PRIORITY ASSESSMENT			
0-50	NONE			
50-150 150-300	LOW MEDIUM			
300-450	HIGH			

Ranking Score:

Priority Assessment: NONE

POTENTIAL HAZARDOUS WASTE PRELIMINARY ASSESSMENT ~ EPS FORM 3012-I

Site No. ALD 00 4017729 Site Name Pullman STP.

EPS ANALYST/REVIEWER CHECKLIST

Instructions:

To be used in conjunction with EPA Form 2070-12 (7-81). Attach on inside front o site folder. Initial and date for all assessment entries under appropriate part/subpart as completed. initial/date in black for final assessment; in red i higher level (additional) assessment is in order. Follow same procedure for

review process.

Review Codes:

1-Toxicology Review; 2-Chemical Review; 3-Ecology Review; 4-Chemical Engineer Review; 5-Geotechnical Review; 6-Project Manager Review; 7-Final Review

1. ANALYST/REVIEW STATUS Form 2070 Analyst/ Review Review Review Review Review Review Review Part Number Date Code 1 Code 2 Code 3 Code 4 Code 5 Code 6 Code 7 1.I.-VI. 7 9/10/84 LUW 910 2.I. 2.II. 2.III. 2.IV. 2.V. \mathfrak{ID} . 2.VI. 3.I. 3.11.A 3.II.B 3.II.C 3.II.D 3.II.E 3.II.F 3.II.G 3.II.H 3.II.I 3.II.J 3.11.K 3.II.L 3.II.M 3.11.N 3.II.O 3.II.P 3.III. 3.IV. 3.V.

^{*}No further assessment/review required, enter NA

POTENTIAL HAZA PRELIMINARY PART 1 - SITE INFORMA	Y ASSESSM	01 ST	1. IDENTIFICATION OUT STATE DZ SITE NUMBER AL D 004017729		
II. SITE NAME AND LOCATION					
01 SITE NAME /Legal, common or descriptive name of site)			PECIFIC LOCATION IDENTIF	HER	
PULLMAN STANDARD DIVISION OF PULLMAN IM	04 STATE 105		A4TH ST	7 TOTCOUNTY OB CONC	
BESSEMER OPCOORDINATES LATITUDE LONGITUDE	1 1		JEFFERSON	CODE DIST	
33 24 35 085 5648					
TO DIRECTIONS TO SITE (Starting from nearest public road) 24TH. ST. TURN TAKE 9 TH AVE NE TO 24TH. ST. TURN TAKE, AT THE GATE ENTRANCE	RIGHT.	STREET	r dead ea	IDS AT 5TH	
III. RESPONSIBLE PARTIES					
O1 OWNER (M known)	5	iainess, malling, resi			
TRINITY INDUSTRIES, INC	4001	LRVING	BLVD BO	x 10587	
03 CITY	04 STATE 05	7IP CODE	1	[
DALLAS	1x 7	5207	12141631-44	30	
07 OPERATOR (If known and different from owner)	08 STREET (B)	iziness mailing, resi	dential)		
PULLMAN STANDARD, DIVISION OF TRINITY IND.	5 15 A	ve, 4	24 St.	R T	
BESSEMER	AL 3		1205 425-37	40	
13 TYPE OF OWNERSHIP (Check one) A. PRIVATE [] B. FEDERAL.		L. C. STATE	LID COUNTY ELL	E. MUNICIPAL	
(Agency name)				2.1110.1110.11.12	
☐ F. OTHER:		(i) G. UNKNO			
14 OWNER/OPERATOR NOTIFICATION ON FILE (Check an Inni apply) A. RCRA 3001 DATE RECEIVED: 1/1/1/10 MONTH DAY YEAR B. UNCONTROL	LED WASTE SI	TE ICERCLA 103 c	DATE RECEIVED:	I I C. NONE	
IV. CHARACTERIZATION OF POTENTIAL HAZARD				**************************************	
O1 ON SITE INSPECTION YES DATE 1 84	A CONTRACTO		STATE LID.O	THER CONTRACTOR	
CONTRACTOR NAME(S):					
03 YEARS OF OPER A. ACTIVE B INACTIVE FI C UNKNOWN	RATION 1929 BEGINNING YEAR	ENDING YI	L: UNK	NOWN	
04 DESCRIPTION OF SUBSTANCES POSSIBLY PRESENT, KNOWN, OR ALLEGED TOLUGNE, XYLENE, WASTE PAINT	BE CHINNING YEAR	ENGINGTI	- An		
OS DESCRIPTION OF POTENTIAL HAZARD TO ENVIRONMENT AND/OR POPULATION NONE. WAGTE: MATERIALS WERE REMOVED CLEANUP OF THE SITE WAS CONFIRMED BY AS OF SEPT. 1, 1984 OPERATIONS RESUMED DITHEY WILL BE OPERATIONS AS GENERATORS ON	ADEM	LNTERIM HE OWN	STATUS WA ERSHIP OF TA	s withdrawn. Bwity Industries	
V. PRIORITY ASSESSMENT		~			
O1 PRIORITY FOR INSPECTION (Check one III high or medium is checked - omplete Part 2 - Weste Info LT A HIGH	anation and Fait 3 - B available basis)	D. NONE	fous Conditions and Bucklenty: raction needed, complete/current	t disposition form!	
VI. INFORMATION AVAILABLE FROM					
01 CONTACT 02 OF Agency (Ingani	ration)			103 TELEPHONE NUMBER	
STEVE MAURER SCH ADEN	1			५०८ २७१-७७३	
04 PERSON RESPONSIBLE FOR ASSESSMENT 05 AGENCY	OB ORGANIZA	ITION	107 TELEPHONE NUMBE	FR OBDATE	

EPS

1601 922-8242

Q	

POTENTIAL HAZARDOUS WASTE SITE

				IFICATION
01	Sī	ΑĪ	E	02 SITE NUMBER
ł			- 1	

WEPA			PRELIMINARY ASSESSMENT PART 2 - WASTE INFORMATION				
ATES, QUANTITIES, AN	D CHARACTER	ISTICS					
O1 PHYSICAL STATES (Check all that apply) L A SOLID B POWDER, FINES G GAS O2 WASTE QL (Meass TO TO		TITY AT SITE of waste quantities a indecendanti	A TOXIC E SOLU B CORROSIVE F INFEC C RADIOACTIVE G FLAM		UBLE LI HIGHLY VOLATILE CTIOUS J EXPLOSIVE MMABLE K. REACTIVE FABLE L. I. INCOMPATIBLE		
(Specify)	ł				M. NOT A	PPERCABLE	
YPE			<u> </u>				
SUBSTANCE N	AME	01 GROSS AMOUNT	02 UNIT OF MEASURE	03 COMMÉNTS			
SLUDGE							
OILY WASTE							
SOLVENTS							
PESTICIDES							
OTHER ORGANIC CH	IEMICALS						
INORGANIC CHEMIC	ALS						
ACIDS							
BASES							
HEAVY METALS		<u></u>					
			,			T OF MEASURE OF	
02 SUBSTANCE N	AME	03 CAS NUMBER	04 STORAGE DISE	POSAL METHOD	05 CONCENTRATION	06 MEASURE OF CONCENTRATION	
		 	<u> </u>		ļ		
·		 			 		
		<u> </u>				 	
		 			ļ		
							
		_			ļ	 	
		 	<u> </u>			↓	
		<u> </u>			<u> </u>		
		 			 		
			ļ		ļ	_	
							
				·		<u> </u>	
		 	 		-		
					ļ	<u> </u>	
		 	 				
		1			<u> </u>	<u> </u>	
CKS (See Appendix for CAS Number	Prs)						
01 FEEDSTOC	K NAME	02 CAS NUMBER	CATEGORY	O1 FEEDST	OCK NAME	02 CAS NUMBER	
			FDS				
			FDS				
			FDS				
			FDS				
OF INFORMATION ICHO	specific references, e.g.	, state files, semple analysis,	eports)				
	FATES (Check all that apply) P. FINES F LIQUID G GAS (Specify) YPE SUBSTANCE N SLUDGE OILY WASTE SOLVENTS PESTICIDES OTHER ORGANIC CHEMIC ACIDS BASES HEAVY METALS DUS SUBSTANCE N 02 SUBSTANCE N CKS (See Appendix for CAS Number) O1 FEEDSTOC	TATES (Check all that apply) P. E. SLURRY P. FINES P. LIQUID P. G. GAS (Specify) TONS CUBIC YARDS NO OF DRUMS YPE SUBSTANCE NAME SLUDGE OILY WASTE SOLVENTS PESTICIDES OTHER ORGANIC CHEMICALS INORGANIC CHEMICALS INORGANIC CHEMICALS OUS SUBSTANCES PERMY METALS OUS SUBSTANCES OUS SUBSTANCE NAME O2 SUBSTANCE NAME CKS (See Appendix for CAS Numbers) O1 FEEDS TOCK NAME	TATES, QUANTITIES, AND CHARACTERISTICS TATES (Check at that apely) PE SUBRAY A, FINES F LIQUID (Specify) TONS CUBIC YARDS NO OF DRUMS TONS CUBIC YARDS NO OF DRUMS YPE SUBSTANCE NAME O1 GROSS AMOUNT SLUDGE OILY WASTE SOLVENTS PESTICIDES OTHER ORGANIC CHEMICALS INORGANIC CHEMICALS ACIDS BASES HEAVY METALS DUS SUBSTANCES (See Appendix for CAS Numbers) O2 SUBSTANCE NAME O3 CAS NUMBER CKS (See Appendix for CAS Numbers) O1 FEEDSTOCK NAME O2 CAS NUMBER	ATES, QUANTITIES, AND CHARACTERISTICS (ATES IGENCE ARIMI JODE) (ATE ORIGINAL CHARACTER ARIMI JODE) (ATES IGENCE ARIMI JODE) (ATER ICENTICAL SHAPPING ATER IGENCE ARIMI JODE) (ATER ICENTICAL SHAPPING ATER IGENCE ARIMI JODE) (ATER ICENTICAL SHAPPING ATER IGENCE ARIMI JODE) (A TER ICENTICAL SHAPPING ATER IGENCE AR	ATES, QUANTITIES, AND CHARACTERISTICS (ATES Check within specify 0.2 WASTE QUANTITY AT THE CHARACTERISTICS Check within specific operations 0.3 WASTE 0	TATES, QUANTITIES, AND CHARACTERISTICS TATES (Circle of the activity) TATES (Circle of the a	

TULLMAN STANDARD.

3	EPA	
~		

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

I. IDENTIFICATION					
01	STATE	02	SITE	NUMBER	


II. HAZARDOUS CONDITIONS AND INCIDENTS (Continued)				
01 D J DAMAGE TO FLORA 04 NARRATIVE DESCRIPTION	02 C OBSERVED (DATE:)	□ P	POTENTIAL.	(1) ALLEGED
01 K. DAMAGE TO FAUNA 04 NARRATIVE DESCRIPTION (Include name(s) of species)	02 D OBSERVED (DATE:)		POTENTIAL	□ ALLEGED
01 [] L. CONTAMINATION OF FOOD CHAIN 04 NARRATIVE DESCRIPTION	02 () OBSERVED (DATE:)	01	POTENTIAL	□ ALLEGED
(Spills/runoff/stending liquids/leaking drums)	02 OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	O F	POTENTIAL	□ ALLEGED
01 (2) N. DAMAGE TO OFFSITE PROPERTY 04 NARRATIVE DESCRIPTION	O2 (3 OBSERVED (DATE:)	F	POTENTIAL	□ ALLEGED
01 □ O. CONTAMINATION OF SEWERS, STORM DRAINS, WWTPs 04 NARRATIVE DESCRIPTION	02 (] OBSERVED (DATE:)	P	POTENTIAL	T ALLEGED
01 □ P. ILLEGAL/UNAUTHORIZED DUMPING 04 NARRATIVE DESCRIPTION	02 () OBSERVED (DATE:)	ΩF	POTENTIAL	[] ALLEGED
05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGI	ED HAZARDS			
III. TOTAL POPULATION POTENTIALLY AFFECTED:				
IV. COMMENTS				
V. SOURCES OF INFORMATION (CRe-specific references, e.g., state Mes, sa	imple analysis reporta)			
		-		

\$EPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT

I. IDENTIFICATION				
01 STATE	02 SITE NUMBER			

PART 3 - DESCRIPTION OF H	AZARDOUS CONDITIONS AND INCIDENT	3	
N. HAZARDOUS CONDITIONS AND INCIDENTS			
01 A. GROUNDWATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED:	02 i ; OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	□ POTENTIAL	□ ALLEGED
01 © B. SURFACE WATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED:	02 □ OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	□ POTENTIAL	[] ALLEGED
01 [] C. CONTAMINATION OF AIR 03 POPULATION POTENTIALLY AFFECTED.	02 [] OBSERVED(DATE:) 04 NARRATIVE DESCRIPTION	D POTENTIAL	☐ ALLEGED
01 D. FIRE/EXPLOSIVE CONDITIONS 03 POPULATION POTENTIALLY AFFECTED.	02 [] OBSERVED (DATE:) 04 NARRATIVE DESCRIPTION	[] POTENTIAL	(ALLEGED
01 ☐ E. DIRECT CONTACT 03 POPULATION POTENTIALLY AFFECTED.	02 OBSERVED (DATE) 04 NARRATIVE DESCRIPTION	E) POTENTIAL	C ALLEGED
01 ☐ F. CONTAMINATION OF SOIL 03 AREA POTENTIALLY AFFECTED:	02 ☐ OBSERVED (DATE) 04 NARRATIVE DESCRIPTION	E POTENTIAL	© ALLEGED
01 [] G. DRINKING WATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED:	02 LJ OBSERVED (DATE) 04 NARRATIVE DESCRIPTION	[] POTENTIAL	Li ALLEGEO
01 C H. WORKER EXPOSURE/INJURY 03 WORKERS POTENTIALLY AFFECTED:	02 [] OBSERVED (DATE) 04 NARRATIVE DESCRIPTION	() POTENTIAL	() ALLEGED.
01 E3. POPULATION EXPOSURE/INJURY 03 POPULATION POTENTIALLY AFFECTED:	02 (1 OBSERVED (DATE) 04 NARRATIVE DESCRIPTION	[] POTENTIAL	i : ALLEGED









DEPARTMENT OF PUBLIC HEALTH

Montgomery, Alabama 36130

State Office Building



() H . a.)

November 4, 1980

<u>M E M O R A N D U M</u>

TO:

Mr. Bernard E. Cox, Jr., Chief, Hazardous Waste Section

Division of Solid and Hazardous Waste

FROM:

Jack Honey Lutt, Chief, Solid Waste Section

Division of Solid and Hazardous Waste

RE:

Landfills on "Eckhardt Report"

The following is a status report on the installation of monitoring wells on existing sanitary landfills listed on the Eckhardt Report:

- Bishop Landfill, Marshall County Wells have been installed and samples collected one time.
- John's Landfill, Jefferson County Wells have been installed and samples collected one time.
- New Georgia Landfill, City of Birmingham Wells have been installed and samples collected one time.
- አ 4) Shannon Landfill, Jefferson County - Wells have been installed and samples collected one time.
- x 5) City of Tuscaloosa Landfill Well locations have been approved and in process of installation.
 - Johnson Landfill, Morgan County Industrial landfill wells have been installed, samples collected and indications are the ground water is contaminated. Darrell Baker is working with Johnson and Mabry Engineering on this landfill. It is my understanding that closure plans have been submitted.
 - 7) City of Decatur Landfill, Old Moulton Road Well locations have been approved and installation should be in the near future.



ALABAMA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT



failing Address: itate Capitol fontgomery, AL July 31, 1984

itate Capitol fontgomery, 6130 105/834-1303

MEMORANDUM

Teld Offices:

TO:

BUDDY COX BEC

FROM:

DAVID HAGAN

1. O. Box 953 Fecalur, AL 5602 95/353-1713

RE:

Unresolved Withdrawal Requests

Init 806, Building 8 25 Oxmoor Circle tirmingham, AL 5209 05/942-6168 The following facilities in the Birmingham area have been inspected by the writer within the last month and were found to be no longer treating, storing or disposing of hazardous wastes:

358 Midmost Drive tobile, AL 6609 35/343-7841 Pullman Standard
Bessemer (ALD 004 017 729)

Pullman Standard has been closed for the past three (3) years. It was recently bought by Trinity Industries, Inc. of Dallas, Tx., and will reopen in August, 1984 employing less than 200 people. Hazardous wastes generated will be solvents (D001) and paint chips (D007). The facility plans to operate as a generator with less that 90 days storage, shipping all hazardous wastes to Diaz Refinery in Arkansas (ARD 092 915 735).

Exide Corporation
Bham (ALD 078 975 331)

Exide's Bham Service Center was closed in 1981 and the building is presently occupied by the Heldor Seablue Company. All hazardous wastes were removed by the time the facility closed down according to a June 6, 1982 letter from Exide to ADEM.

Gulf Oil Company
Bham (ALD 000 604 249)

This facility operates as a generator with less than 90 day storage. Gulf generates leaded tank bottoms when fuel storage tanks are periodically cleaned. The waste is removed from the tanks directly into the transport vehicle for off-site disposal.

The above (3) three facilities are being sent withdrawal letters.

Site Name: PULLMAN STANDARD CO.
Site Number: ALD 004 017729
Owner: TRINITY INDUSTRIES, INC.
Operator: PULLMAN STANDARD, DIVISION OF TRINITY INDUSTRIES
Site Status: Active / Inactive / Unknown
Priority: High Medium Low None
3. FINAL DISPOSITION
I. EPS Final Review - Date: 9/10/84 Comments:
Site Inspection Required / Yes / No
II. ADEM Review - Date: 10/10/84 SCM Comments:
Follow-up Action Required // Yes // No
III. Final Disposition: Review & revise Date: Edited & correct Date:
Transmitted Date:
File close-out Date: Initiate site
inspection Date:
4. ADDITIONAL COMMENTS (ONGOING & FINAL)
TO THE BEST OF OUR KNOWLEDGE THIS
IS A RCRA FACILITY ONLY.
*



DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

M. Skinson

ALABAMA

failing Address: tate Capital funtgon ary. Al. 6130 05/834-1303

July 30, 1984

Mr. Hugh Bryant Pullman Standard Company P. O. Box 428 Bessemer, Al 35021

ield Offices

O Box 953 ecatur. At 5602 25 353-1713

nit 806 Blanding 8 25 Oxmoor Cacle irming/rans, AL 5209 35-942-6168

Re:

Facility ALD 004 017 729

Dear Sir:

358 Midmost Drive chite, AL 5009 35:343-7841

This is to acknowledge receipt of your request to withdraw your Part A, RCRA Permit Application. Since Alabama has Phase I Authorization, it will be our responsibility to determine if your request should be honored.

Based upon the information you supplied, it appears that your facility is no longer treating, storing, or disposing of hazardous waste and is, therefore, not subject to Alabama's Hazardous Waste Management Regulations. Therefore, your request to withdraw your Part A Application is granted. However, you should be aware that as a generator of hazardous waste you must meet the generator requirements of RCRA as specified in 40 CFR 262.

You should be aware that your request to withdraw interim status means that you may not treat, store, or dispose of hazardous waste without a permit issued under the authority of Code of Alabama 1975, Section 22-30-12, as amended, and the Regulations adopted thereunder.

Should you have questions or comments, please feel free to contact this office.

Sincerely,

Bernard/E/. Cox, Jr., Chief

Industrial and Hazardous Waste Section

Land Division

cc: Mr. James Scarbrough USEPA - Region IV

> Mr. Jerry Riddles Trinity Industries, Inc.

TRINITY INDUS: _ XIES, INC.



July 17, 1984

Mr. David Hagan Alabama Department of Environmental Management Industrial and Hazardous Waste Section State Cap Montgomery, Alabama 36130

> RE: Pullman Standard MFG., 5th Ave. and 24th Street, Bessemer, Jefferson County, Alabama 35020

Dear Mr. Hagan:

Per our phone communication you will have attached to this cover letter a copy of Pullman Standard MFG. "Hazardous Waste Management Program & Guidelines". This program will cover all type of hazardous waste activities that Pullman may preform with Trinity Industries, Inc. You may find items in the program which Pullman may never get involved with, but Trinity is very diversified and depending on the economy we can change product lines in a short time.

The attached program does not have the weekly inspection of waste holding sites because this is worked out depending on the type of guard set up we have at each facility. The only other remaining are not covered in this program is the filling out of Waste Manifest. As you know the market is full of Waste Manifest depending what state you ship to or out of. Each manifest is different so at this time all maifest are filled out by me in Dallas and mailed to the plant and instructions are given to the person in charge of shipping. On or after September 24, 1984 when the uniform waste manifest go into effect I will revise not only Pullmans waste management programs but all Trinity owned plants manuals.

I am still looking froward to a updated copy of Alabama's "Hazardous Waste" rules from you as per our phone communication. Please address all correspondance to my attention, and if you have any questions please let me know.

Thank-you

Jerry Raddles, A.S.P., C.H.C.M. Assistant Corporate Safety Director

JR:cc

Attachment:

cc: Hugh Bryant-Pullman Bessemer



5th Avenue and 24th Street Bessemer, Alabama 35020 (205) 425-3231

March 12, 1984

Mr. B. E. Cox, Jr., Chief Alabama Dept. of Environmental Management Land Program . State Capital Montgomery, AL 36130

Dear Mr. Cox:

In submitting our EPA Annual Report Form for 1983 as per your recent letter of instruction, please note that I have marked a zero under Items "C", "D" and "VI." Since the plant status is the same as it was in late 1980, 1981 and 1982, i.e., no production and totally shutdown, we have neither purchased, stored, used, nor generated any hazardous material of any kind. This was discussed with Mr. Joe Brewer by telephone on 3-9-83, and on his recommendation, I am including a cover letter with the Annual Report.

If there are any questions, please give me a call.

Very truly yours,

PULLMAN STANDARD

H. S. Bryant, Jr. General Manager

HSBJr;ec

Attachments





State of Alabama

DEPARTMENT OF PUBLIC HEALTH

State Office Building Montgomery, Alabama 36130

May 13, 1982



بر الربوء ا

IRA L. MYERS, M.D. STATE HEALTH OFFICER

Mr. James H. Scarbrough, Chief Residuals Management Branch USEPA-Region IV 345 Courtland Street Atlanta, Georgia 30365

Re: Part A Status

Dear Mr. Scarbrough:

Enclosed are copies of letters from facilities requesting a change in their original Part A applications. These facilities are listed by name and I.D. number for quick reference. The states recommendation will also be noted by facility:

Georgia-Pacific Corporation- Belk, Alabama-ALD063669626-State concurs with withdrawal request.

Georgia-Pacific Corporation-Talladega, Alabama-ALD063662597-State concurs with withdrawal request.

Pullman-Standard-Bessemer, Alabama-ALD004017729-EPA and State have written status request letters to company. Response to State request enclosed. Facility not in use since October, 1980, due to plant shutdown. Company may reopen this summer so State recommends that Part A not be withdrawn at this time.


If you need additional information regarding these facilities, please contact this office.

Sincerely,

Bernard E. Cox, Jr., Chief Industrial and Hazardous Waste Section Division of Solid and Hazardous Waste

BEC:DLR:rc







Pullman Standard



5th Avenue and 24th Street Bessemer, Alabama 35020 (205) 425-3231

May 6, 1982

Mr. David L. Robertson Pollution Control Specialist Industrial and Hazardous Waste Section Division of Solid and Hazardous Waste Department of Public Health State Office Building Montgomery, AL 36130

Dear Mr. Robertson:

RE: Closing of Storage Area (Paint) at Bessemer Plant

As stated in our letter to Mr. Harvanek, dated August 10, 1981, our plant has not been in production since October 1980, and was officially closed February 28, 1981.

There has been no painting operations since the October 1980 date and no purchase or delivery of any paint for this plant two months prior to that date. The remaining or unused quantities of paint on hand, after production ceased, were sold and removed from site to a company in Fultondale, AL, for reclaiming purposes. (So stated in our letter to you dated September 17, 1980 from D. F. Winn, Plant Engineer, Pullman Standard.)

The storage area in field at north end of plant is void of any containers of paint, and the grounds have been cleaned up for at least a one year period. Also cleaned up during that same time were the floors and paint equipment in building where paint operations had been performed.

We feel that in view of the steps taken, and considerable cost incurred toward clean up and removal of paint storage from our plant premises, that there is nothing further to be done in order to comply with Hazardous Waste Management Regulations.

We would like to maintain the Part "A" of our Hazardous Waste Permit active as you recommended.

Mr. David L. Robertson

RE: Closing of Storage Area (Paint) at Bessemer Plant

May 6, 1982 Page Two

When, and if in fact, we do resume operations at this plant location, plans are to reapply for our Hazardous Waste Permit.

Please contact this office if you have any questions.

Very truly yours,

PULLMAN STANDARD

H. S. BRYANT, JR. General Manager

HSB:ec

cc: D. F. Winn

4E:CP

Mr. H. S. Bryant, Jr. General Hanager Pullman Standard 5th Avenue and 24th Street Bessemer, Alabama 35020

PULLHAD SUARIARD

EPA I.D. Number ALD004017729 - Request for withdrawal of RCRA Permit Application at Bessemer, Alabama site.

Dear Mr. Gosnell:

Reference your letter of August 10, 1981, subject as above.

operations at the above site, you with the closure requirements of 40 CFR Part 265, puppert G, Paragraphs 265.110 through 265.115, to ensure that closure takes place in such a manner that (a) minimizes the need for further maintenance, and (b) controls, minimizes or eliminates the post-closure escape of hazardous waste to the environment.

These requirements include:

These requirements include the submission to EPA and the State of a closure facility, the removal or disposal of all hazardous wastes within 90 days after receipt of approval of the closure plan, the disposal or decontamination of all facility equipment and structures, and the submission of certification both by the owner or operator and by an independent both by the owner or operator and by an independent registered professional will be engineer that the facility has been closed in accordance with the specific tions in the approved closure plan (see the detailed see the facility has been facility has been closed in accordance with the specific tions in the approved closure plan (see the detailed see the facility has been facility has been closed in accordance with the specific tions in the approved closure plan (see the detailed see the facility has been closed in accordance with the specific tions in the approved closure plan (see the detailed see the detailed engineer that the facility has been closed in accordance with the specifications tions in the approved closure plan (see the cited paragraphs for the detailed requirements). With the remaining

Any questions may be directed to the undersigned at 404-881-2017.

Sincerely yours.

John M. Harvanek III. P.E. Regional Project Officer For RCRA Notifications

cc: Mr. Don Cooper, Alabama Water Improvement Commission

bcc: Mike Taimi Keith Castro Jim Wilburn Bob Tallini John Herrmann

F - City Supply Co. - Jeff Co., Division of Pullman Incorporated



Pullman Standard

5th Avenue and 24th Street Bessemer, Alabama 35020 (205) 425-3231

September 17, 1980

Mr. David L. Roberson
Alabama Department of Public Health
Division of Solid Waste
& Vector Control
Environmental Health Adm.
State Office Building
Montgomery, Alabama 36130

Dear Mr. Roberson:

In response to your telephone conversation of September 15, 1980, this is to notify you that the scrap paint hauled from the plant by Moore Coal Company is to be delivered to City Supply Company at Fultondale. It is our understanding that this material is to be recycled for future use as paint.

Should you have any questions, please feel free to call.

Very truly yours,

PULLMAN STANDARD

D. F. Winn

Plant Engineer

JTG/dp

RECEIVED

SEP 18 100

ST TWENT DIVISION OF SOLID WASTE & VECTOR CONTROL

August 12, 1980

Mr. John R. Harris Facilities Engineer Pullman Standard P. O. Box 428 Bessemer, Alabama 35020

Dear Mr. Harris:

Mr. Taylor and I appreciate the time you spent with us on August 7, 1980, discussing the new federal hazardous waste regulations and also the waste streams from your company. I am sorry that Mr. Wynn, your plant engineer, could not be present.

During our discussion, you stated that Moore Coal Company of Bessemer picked up your paint wastes and disposed of them. We request that you notify this office in writing as to the location of your disposal sites that Moore Coal uses for your wastes. This request is to determine if proper disposal is being achieved. Under the new regulations, the wastes from your company are your responsibility from generation to final disposal, if they are hazardous. A review of all your waste streams and ultimate disposal should be performed.

I am enclosing the listings you requested on hazardous waste disposal sites. I hope they can be of some use if your company needs one. New sites may become available so it will be up to your company to find a site that will fit its needs, and to assure that the site is permitted for your perticular wastes.

Please review the regulations and particularly the "Criteria for Identification of Hazardous Wastes". If, after reviewing the materials, you have any questions, please feel free to contact this office.

Sincerely,

David L. Roberson, Environmentalist Division of Solid Waste & Vector Control Environmental Bealth Administration

DLR:bw

cc: Mr. Frank Phillips
Jefferson County Health Department

Enclosure

- 8) City of Decatur Landfill, Highway 31 Well locations have been approved and installation should be in the near future.
- 9) Martintown Landfill, City of Scottsboro Well locations have been approved, presently advertising for bids for construction.
- 10) Crow Mountain Landfill, Jackson County Landfill in process of being closed out, should be completed In about thirty days.
- 11) Magnolia Landfill, Baldwin County Well locations have been approved along with engineering plan. Well construction should be completed by February 23, 1931.
- 12) Red Hill Landfill, Baldwin County No status, ground water criteria on ODI carried over to FY-81. No projected date for installation of wells.
- 13) Marengo County Landfill No status, no projected date for installation of wells.
- 14) Crenshaw County Landfill Well locations have been approved, construction should be in near future.
- 15) City of Montgomery Landfill Well locations have been approved, construction should be completed in the near future.

All of the above landfills were listed for evaluation on the "Open Dump Inventory" in FY-80. Insufficient time, however, did not allow for well construction on all the sites. Johnson's Landfill was the only site inventoried that had monitoring wells installed with sufficient time to collect samples before the September 30, 1980 deadline. The ground water criteria was carried over on all the other sites to FY-1981 and are included in the ODI work plan approved by EPA.

1. 1. 1

U.S. ENVIRONMENTAL PROTECTION AGENCY OFFICE OF EMERGENCY AND REMEDIAL RESPONSE C E R C L A

PAGE: 1330 RUN DATE: 85/06/03 RUN TIME: 19:06:17

M.2 - SITE MAINTENANCE FORM

	* ACTION: _
EPA ID: ALD004017729	
SITE NAME: PULLMAN STANDARD CO SOURCE	: H *
STREET: 5TH AVE & 24TH ST CONG DIST: 07	*
CITY: BESSEMER ZIP: 3502	1 *
CNTY NAME: JEFFERSON CNTY CODE: 073	*
LATITUDE: 33/24/35.0 LONGITUDE: 085/56/48.0	* _/_/
SMSA: 1000 HYDRO UNIT: 03160112	*
INVENTORY IND: Y REMEDIAL IND: Y REMOVAL IND: N FED FAC	IND: N *
NPL IND: N NPL LISTING DATE: NPL DELISTING DATE:	*/ :
APPROACH: SITE CLASS:	* :
SITE/SPILL IDS:	*
RPM NAME: RPM PHONE:	*
DIOXIN TIER: REG FLD1: REG FLD2: 6	*
RESP TERM: PENDING () NO FURTHER ACTION (X)	* PENDING (_) NO FURTHER ACTION (_)
ENF DISP: NO VIABLE RESP PARTY () VOLUNTARY RESPONSE ()	* :
ENFORCED RESPONSE () COST RECOVERY ()	* :
SITE DESCRIPTION:	
	*
	*
	*
	*

U.S. ENVIRONMENTAL PROTECTION AGENCY OFFICE OF EMERGENCY AND REMEDIAL RESPONSE C E R C L A

PAGE: 1331 RUN DATE: 85/06/03 RUN TIME: 19:06:17

M.2 - PROGRAM MAINTENANCE FORM

				* ACTION: _	۴
SITE:	PULLMAN STANDAR	р со			
EPA ID:	ALD004017729	PROGRAM CODE: H01	PROGRAM TYPE:	* _ '	×
PROGRAM	QUALIFIER:	ALIAS LINK :		* :	×
PROGRAM I	NAME: SITE	EVALUATION		*	×
DESCRIPT	ION:				
				*	×
				*:	×
				*	×
				*	¥

U.S. ENVIRONMENTAL PROTECTION AGENCY OFFICE OF EMERGENCY AND REMEDIAL RESPONSE C E R C L A

PAGE: 1332 RUN DATE: 85/06/03 RUN TIME: 19:06:17

M.2 - EVENT MAINTENANCE FORM

			* ACTION: _		×
SITE: PULLMA PROGRAM: SITE E	N STANDARD CO VALUATION				
EPA ID: ALDOO4	017729 PROGRAM CODE: HO1	EVENT TYPE: DS1			
FMS CODE:	EVENT QUALIFIER:	EVENT LEAD: E	* _		_ *
EVENT NAME: DI	SCOVERY	STATUS:	*		×
DESCRIPTION:					
			*		×
			*		*
			*		*
			*		· · · · · · · · · · · · · · · · · · ·
ORIGINAL	CURRENT	ACTUAL			
START:	START:	START:	* _/_/_	_/_/_	_/_/_ *
COMP :	COMP :	COMP : 80/08/01	* _/_/_	_/_/_	_/_/ *
HQ COMMENT:					
			*		······································
RG COMMENT:					
			*		
COOP AGR #	AMENDMENT # STATUS	STATE %			
			*		,

U.S. ENVIRONMENTAL PROTECTION AGENCY OFFICE OF EMERGENCY AND REMEDIAL RESPONSE C E R C L A

PAGE: 1333 RUN DATE: 85/06/03 RUN TIME: 19:06:17

M.2 - EVENT MAINTENANCE FORM

			* ACTION: _		×
SITE: PULLM PROGRAM: SITE	AN STANDARD CO EVALUATION				
EPA ID: ALDOO	4017729 PROGRAM CODE: H01	EVENT TYPE: PA1			
FMS CODE:	EVENT QUALIFIER:	EVENT LEAD: 5	* _	•	_ *
EVENT NAME: P	RELIMINARY ASSESSMENT	STATUS:	*		_ *
DESCRIPTION:					
			*		*
			*		*
			*		*
			*		*
ORIGINAL	CURRENT	ACTUAL			
START:	START:	START: 85/03/01	* _/_/_	_/_/_	_/_/_ *
COMP :	COMP :	COMP : 85/03/01	* _/_/_	_/_/_	_/_/_ *
HQ COMMENT:					
			*		*
RG COMMENT:					
			*		· · · · · · · · · · · · · · · · · · ·
COOP AGR #	AMENDMENT # STATUS	STATE %			
			*		•

U.S. ENVIRONMENTAL PROTECTION AGENCY OFFICE OF EMERGENCY AND REMEDIAL RESPONSE C E R C L A

PAGE: 1334 RUN DATE: 85/06/03 RUN TIME: 19:06:17

M.2 - COMMENT MAINTENANCE FORM

SITE: PULLMAN STANDARD CO	
EPA ID: ALD004017729	
COM NO COMMENT	ACTION
001 PART A-ON FILE	*

C.EDA	POTENTIAL HAZARDOUS WA	STE SITE	~	REGION SITE N	_	- 0
VLIA	TENTATIVE DISPOSIT	ION		1- Hrn	00401	1729
	ardous Waste Log File and submit ement Task Force (EN-335), 401 h				ncy, Site T	racking
	I. SITE IDENT	IFICATION			_	
A. SITE HAME	Dir id Pulland	B. STREET	fve. 23	HZ ELL		
C. CITY Passamer	Vacant of Careers	D. STATE		E. ZIP COD		
1 estration 1	77	1/4			<u> </u>	
Indicate the recommended action(II. TENTATIVE s) and agency(ies) that should be		shing (Y) is the			
Indicate the recommended bettom	ay and agency, resy ma. Should be	HIVOIVED BY IN	A III LIC	ACTION A		
RE	COMMENDATION	!	MARK'X' EP			PRIVATE
A. NO ACTION NEEDED NO HAZ	ARD					\$75 5 .
B. INVESTIGATIVE ACTION(S) NEE	DED (If yes, complete Section III.)					
C. REMEDIAL ACTION NEEDED (II	yes, complete Section IV-)					
	D (if yes, specify in Part E whether the or the State and what type of enforcement					
E. RATIONALE FOR DISPOSITION		- 0	0 00	THE O		-0.1
Creaming of set	e in 1980 col	fund.	son Ha	DEH, a	יאון פט	, , , , , , , , , , , , , , , , , , ,
disposal.						
0						
F. INDICATE THE ESTIMATED DAT	E OF FINAL DISPOSITION	G. IF A CASE	DEVELOPMENT	PLAN IS NECESS	ARY, INDIC	ATE THE
(mo., day, & yr.)		ESTIMATEI (mo., day, &		CH THE PLAN WIL	L BE DEVE	LOPED
			•			
H. PREPARER INFORMATION						_
1. NAME (1) _ \ \ .		2. TELEPHO		. i	E (mo., day, c	_
Oton W.	1 - 75	57-22	-34 11 6-	6-9		
A. IDENTIFY ADDITIONAL INFORMATION NEEDED TO ACHIEVE A FINAL DISPOSITION.						
						i
B. PROPOSED INVESTIGATIVE AC	TVITY (Detailed Information)	1	1			
	2. SCHEDULED 3. TO BE DATE OF PERFORMED BY	4.	1			:
1. METHOD FOR OBTAINING NEEDED ADDITIONAL INFO.	ACTION (EPA, Con- (mo, day, & yr) tractor, State, etc.)	ESTIMATED MANHOURS	1	5. REMARKS		
A. TYPE OF SITE INSPECTION						
<u> </u>			<u> </u>			
(2)		-				
		 	<u> </u>			
(3)						
b. TYPE OF MONITORING (1)						
(2)					-	
C. TYPE OF SAMPLING			 			
			L			
(2)						

Continued From Front					·			
		THY NEEDED	and PART	BORO	POSED INVES	TIGATIVE	EACTIVI	TY (Continued)
d. TYPE OF LAB ANALYS	SIS					•		····
(2)				1 -				
e. OTHER (specify)				+				
(1)	_	_ _		_	_ _			
(2)			2					
C. ELABORATE ON ANY D INVESTIGATIVE WORK.	FITHE INFORM.	ATION PROVIDE	L IN PART E	s (on tro	n' <u>&</u> above, AS l	NEEDED T	O IDENTI	FY ADDITIONAL
D. ESTIMATED MANHOURS	BY ACTION AC	iENCY						
S. COLIMATES MANHOURS	- ACHUN AG	2. TOTAL EST MANHOURS		Ī				2. TOTAL ESTIMATED MANHOURS FOR
1. ACTION AGEN	CY	NVESTIGA ACTIVIT	TIVE		1. ACTION A	GENCY		INVESTIGATIVE ACTIVITIES
B. EPA				b. STA				
C. EPA CONTRACTOR]		d. 074	HER (specify)	_ -		
			. REMEDIA	L ACT	IONS			
		On Site & Off-Si	ite) List all	em erg er	ncy actions need			er immediate control, e.g., re-
	2. EST	. 3. EST.	4.				T	
1. ACTION	START	T END	ACTION AG (EPA, Sta Private P	nte,	5. ESTIMATE	D COST	INDICA	FY 311 OR OTHER ACTION; ATE THE MAGNITUDE OF HE WORK REQUIRED
					s			
					s			
			1		s			
			 		\$			
					\$			
			1		s	<u> </u>		
B. LONG TERM STRATEGY See instructions for a list						emoval, gro	und water	monitoring wells, etc.
	-				T		Τ	
1. ACTION	2. EST START DATE	T END	4. ACTION ACEPA, So Provate P	tate	5. ESTIMATE	D COST	INDICA	FY 311 OR OTHER ACTION; ATE THE MAGNITUDE OF HE WORK REQUIRED
	aro, a ey	,	, , , vale p	-1.57	s		1	ACTION REQUIRED
					s			
					s			
					s		1	
					s		†	
		_ +	1,					
C. FETIMATER MANUSCO	LANDSCOT	ACTION	<u></u>		\$		<u> </u>	
C. ESTIMATED MANHOURS 2. TOTAL	EST.		7			2. TOTAL		
1. ACTION REMEDI AGENCY ACTIVITI	FOR 3.70	OTAL EST. COST FOR DIAL ACTIVITIE	1 1.	ACTION	AGENCY	MANHOU REME ACTIVI	RS FOR	3. TOTAL EST. COST FOR REMEDIAL ACTIVITIES
a. EPA			b. sT/					
C. PRIVATE PARTIES			d. OT	HER (SP	ecify)			

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT EPS FORM 3012-III

INDUSTRIAL NARRATIVE SHEET

1. Site Identification:

Site number: ALD004027729

Site name: Pullman Standard, Division of Pullman Inc.

Site county: Jefferson

2. Industrial Narrative Summary:

Company Name: Pullman Standard, Division of Pullman Inc.

Address: 5th Avenue and 24th Street

Bessemer, AL 35020

Telephone No.: 205/425-3240

Contact: Hugh Bryant

Discussion: Pullman Standard fabricates steel in the production of railcars. In this process they are involved in welding, riveting, bolting, shot blasting, and painting. Their waste products include waste paint as well as the solvents toluene and xylene. This facility closed during 1980 and at that time, they spent both time and money to remove all the remaining waste products from the site. They did not withdraw from interim status in the hope they would be able to reopen or be bought out. In late 1983, they were purchased by Trinity Industries of Dallas, Texas, and operations have resumed as of September 1, 1984. At this time they hope to operate under the Pullman name and remain a division of Trinity Indust. They will operate as a generator only.

For approximately 10 years prior to ceasing operations, waste materials were kept in drums at the site. Waste paints that were left over were kept in the original drum and placed in their yard. Before that time, waste paint materials were hauled from the site every 5-6 years. The company representative believed that the materials were burned. Before the mid 1960's, the painting operations were done outside and they did not use a great deal of solvents. In or around 1965, they built a building to house the painting operations and at that time they began using more solvents to clean the reusable stencils when they got clogged. Disposal of these materials is

uncertain. To the best of knowledge, there has been no on-site disposal of hazardous waste.

Withdrawal from interim status has been requested and granted. Before being allowed to withdraw from interim status, a representative from ADEM visited the site and evaluted the cleanup operations. At that time, they found the site to be clean with no evidence of any on-site disposal or unregulated areas.

3. <u>Disposition</u>:

No further action required at this site under this program. To their best knowledge, there has been no on-site disposal of hazardous wastes at this site and all remaining wastes were removed from the site when they closed in 1980. The company has withdrawn from interim status and has reopened recently under new ownership. They will be regulated as a generator only by ADEM.

4. Comments:

Specific information about disposal of the wastes was unavailable at this time. This reviewer believes that the potential exists that these waste materials were taken to local landfills in operation during the time period this company operated.

CLO. HUMO, A center / can once D 0 0 4 IV. DESCRIPTION OF HAZARDOUS WASTES ROCESS : (onter) 15,000 F 0 1 7 G -0-0 5 F 0 G 3 UO 5 2 750 G 4 2,500 U 2 2 0 G 5 U 2 3 9 1,200 G 6 7 8 9 10 11 12 13 15 16 17 18 19 **2**d PA Form 3510-3 (6-80)

3 OMB 110, 15**3-880004**



1927 LAKESIDE PARKWAY SUITE 614 TUCKER, GEORGIA 30084 404-938-7710 ATTACHMENT 2

Mrkn

C-586-3-9-11

March 8, 1989

Mr. A.R. Hanke
Site Investigation and Support Branch
Waste Management Division
Environmental Protection Agency
345 Courtland Street, N. E.
Atlanta, Georgia 30365

Date:	
Site Disposition:	
EPA Project Manager:	

Subject:

Preliminary Reassessment

Pullman Standard

Birmingham, Jefferson County, Alabama

EPA ID No. ALD004017729

TDD No. F4-8811-20

Dear Mr. Hanke:

FIT 4 conducted a preliminary reassessment of Pullman Standard Company in Birmingham, Alabama. The assessment included a review of EPA and state file material, completion of a target survey and a drive-by reconnaissance of the facility on December 1, 1988.

Pullman Standard has been fabricating steel in the production of railroad cars since 1929 (Ref. 1). This process involved welding, riveting, bolting, shot blasting, and painting. Waste products include waste paint and solvents including toluene and xylene. This facility closed in 1980 at which time all remaining waste products were removed from the site. At that time, Pullman Standard did not withdraw their RCRA interim status in the hope that the facility would be able to reopen or be bought out. In late 1983, Trinity Industries of Dallas, Texas, purchased the facility and operations resumed on September 1, 1984 (Ref. 1).

For approximately 10 years prior to ceasing operations, waste materials were kept in drums at the facility. During this time waste paints were kept in their original drums and placed in the facility yard. Before 1970, the waste paint materials were hauled from the site every 5-6 years. Before the mid 1960's, the painting was done outside and use of solvents was limited. In or around 1965, a building was erected to house the painting operations. At that time Pullman Standard began using more solvents to clean the reusable stencils. The method of disposal of these waste materials is uncertain. There are no records indicating any onsite disposal of hazardous waste. Currently, Pullman is classified as a hazardous waste generator under RCRA. The company withdrew its Part B application as a storage facility (Ref. 2).

Pullman Standard is located in the Birmingham Valley physiographic section of the Valley and Ridge Physiographic Province (Ref. 3). The area is characterized by northeast-southwest trending valleys and ridges, which exhibit extensive faulting and folding (Ref. 3, pp. 1, 3). As a result of these structural features vast differences in geologic and hydrogeologic environments occur over distances of only a few miles (Ref. 3, p. 1). Groundwater occurs in solution cavity channels and fracture zones

Mr. A. R. Hanke Environmental Protection Agency TDD No. F4-8811-20 March 2, 1989 - page two

within these tectonically altered rock units (Ref. 4). Recharge to groundwater is by percolation of precipitation. Net annual rainfall for the area is 11 inches (Ref. 5).

Geologic units that occur within a 4-mile radius of the site, in descending order include: the Parkwood Formation, the Floyd Shale; the Hartselle Sandstone; the Pride Mountain Formation; the Tuscambia Limestone, Fort Payne Chert, and Maury Formation; the Chattanooga Shale and Frog Mountain Sandstone; the Red Mountain Formation; the Chickamauga Limestone; the Attalla Chert Conglomerate Member of the Chickamauga Limestone; the Knox Group undifferentiated, the Ketona Dolomite, and the Conasauga Formation (Ref. 6, Maps 19, 20, 26). Together, these units represent an aggregate thickness of over 10,000 feet of sediment. The presence and thickness of any particular rock unit is dependent on its location within this complex structural setting. Extensive faulting and folding has exposed at land surface the previously mentioned formations (Ref. 3, pp. 7-13). This structural complexity differs from the traditional "layer cake" concept of aquifer and confining layer. These aquifers are unconfined at the surficial outcrop, but may be confined at depth (Ref. 3, pp. 18, 19).

If any groundwater supplies in Jefferson County are used, they are primarily derived from rock units having well-developed water-bearing solution and structural features. Within a 4-mile radius of the facility, the Fort Payne Chert, Tuscambia Limestone aquifer and the Bangor Limestone aquifer are considered to have the greatest potential for development as a groundwater resource. These aquifers currently sustain large volume production wells with yields of greater than 150 gpm (Ref. 3, pp. 41, 42). However, these aquifers are not present in the immediate vicinity of the facility (Ref. 6, Maps 13, 14, 20, 21).

The water-bearing rock units underlying the facility are contained within the outcropping Conasauga Formation (Ref. 6, Map 20). The Conasauga Formation is considered to be a good aquifer in the area, and consists of thinly-bedded brownish-gray sublithographic limestone, gray shale, and brownish-gray dolomite (Refs. 4, pp. 96, 97; 6, p. 3). The beds within this formation dip steeply and contain well-developed solution features capable of producing large quantities of water (Ref. 4, pp. 96, 97). Groundwater from the Conasauga Formation occurs at variable depth from surficial springs to wells 600 feet deep (Ref. 3, pp. 60-75).

Surface water runoff from the site would be via two streams that flow to the northwest into Valley Creek. One stream transects the southwest end of the facility property, the other stream is located about 1000 feet northeast of the northeast end of the property (Ref. 7). There are no surface water intakes within 15 miles downstream of the facility (Ref. 8). Valley Creek is not used for fishing (Ref. 9).

Bessemer purchases water from Birmingham, which services the majority of Jefferson County. Birmingham obtains its water from four sources that do not receive drainage from the facility. The intakes are on the Cahaba River (intake is at Elmore Lake, if level is too low, water is drawn from Lake Purdy), Smith Lake (located in Walker County), and Inland Lake (located in Blount County) (Ref. 8). There are no drinking water wells within a 4-mile radius of Pullman Standard.

Mr. A. R. Hanke Environmental Protection Agency TDD No. F4-8811-20 March 2, 1989 - page three

Based on the above-referenced information and enclosures, FIT 4 recommends that no further remedial action be planned for this facility.

Very truly yours,

Bob Tolford
Project Manager

BT/kw

Enclosures

cc: EPA PO


Approved:

Blockery

REFERENCES

- 1. Potential Hazardous Waste Site Preliminary Assessment (EPS forms 3012-II and 3012-111) for Pullman Standard.
- 2. Joe Downey, Alabama Department of Environmental Management, telephone conversation with Bob Tolford, NUS Corporation, December 12, 1988. Subject: RCRA status of four Alabam sites.
- 3. T. B. Moffett, and P. H. Moser, <u>Groundwater Resources of the Birmingham and Cahaba Valleys of Jefferson County, Alabama</u>, Circular 103, (University, Alabama: Geological survey of Alabama, 1978), pp. 1-44.
- 4. W. D. Johnson, <u>Groundwater in the Palozoic Rocks of Northern Alabama</u>, Special Report No. 16, (Geologic Survey of Alabama, 1933).
- 5. U.S. Department of Commerce, <u>Climatic Atlas of the United States</u>, (Washington, D.C.: GPO, June 1968), Reprint: 1983, National Oceanic and Atmospheric Administration.
- 6. J. T. Kidd, <u>Areal Geology of Jefferson County</u>, (Geological Survey of Alabama, Atlas 15, 1979).
- 7. U.S. Geological Survey, 7.5 minute series Topographic Quadrangle Maps of Alabama, <u>Concord</u> 1979; <u>Bessemer</u> 1959 (Photorevised 1970 and 1978), <u>Birmingham South</u> 1959 (Photorevised 1970 and 1978), <u>Greenwood</u> 1959 (Photorevised 1978).
- 8. NUS Corporation, April 26, 1988. Field Logbook No. F4-814 for Reconnaissance of Hayes International Corporation, TDD No. F4-8804-48.
- 9. George Edwards, Vallhala Cemetary, telephone conversation with Bob Tolford, NUS Corporation, December 15, 1988. Subject: Recreational use of Valley Creek.

01001



ATTACHMENT 1